

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13715

Date In:	25 JUN 26	Author:	MGRAY
Promised Date:	03 JUL 26	Stock No:	11435
:	:	Year:	2026
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	FLAGSTAFF MICRO-LITE
:	CHICAGO, IL	Model:	25MBR
Postal/Zip:	60673-1218	Miles/Hrs:	:
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	24 JAN 26	:	:
Delivery Date:	01 APR 26	:	:
InService Date:	:	:	:
Serial#:	4X4TFLB20TZ198245	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
1	COMPLAINT: AWNING OVER BEDROOM SLIDEOUT FABRIC IS RIPPED		W	1021 FORES
	CAUSE: Awning over bedroom slide out is ripped			
	CORRECTION: It will need a new slide topper			
	REQUEST: 2 HOUR			
2	COMPLAINT: CABINET IN BEDROOM KICKPLATE/TRIMPIECE IS COMING LOOSE		W	1021 FORES
	CAUSE: Pop loose from the nails			
	CORRECTION: Pre-drilled holes, put in screws and push it back together, but well need a new facia board which is cracked			
	REQUEST: 1.5			
3	COMPLAINT: BEDROOM WINDOW WANTS TO WALK WHILE BRINGING UP AND DOWN		W	1021 FORES
	CAUSE: The window gets wedged going up and down its the design of the window			
	CORRECTION: Did spray silicone spray in the window track did seem to help but it still will do it from time to time			
	REQUEST: .1			
4	COMPLAINT: IS UNIT PREPPED FOR 5G OR HAVE EQUIPMENT ON HAND IF ON HAND WANTS TO KNOW HOW IT WORKS		W	1021 FORES
	CAUSE: Is unit prepped for 5 g			
	CORRECTION: It is prepped for 5g just has to get the rest of the equipment to make it work I have attached a paper to the work order with what they need. WAS THIS UNIT SUPPOSED TO COME EQUIPED WITH THE WIFI			

Continued on page 2

Work Order : 13715

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
ROUTER? OR IS THAT A CUSTOMER WPURCHASED
ITEM.
5      COMPLAINT:  WOULD LIKE CHANNEL SCAN DONE ON UNIT TO W      1021    FORES
        MAKE SURE IT WORKS WOULD LIKE SHOWN HOW
        TO DO CHANNEL SCAN ON PICKUP IF WORKING
        CAUSE:      1001 CUSTOMER REQUESTED Channel scan 16
                    channels
        CORRECTION: No correction needed at this time
6      COMPLAINT:  STOVE TOP GLASS BROKEN FROM PUTTING DOWN W      1021    FORES
        WHILE BURNERS STILL WARM
        CAUSE:      Glass stove, top cover, shattered
        CORRECTION: Will need a new stove top cover
        REQUEST:    .2
7      COMPLAINT:  PLASTIC RING AROUND METAL FOR SLIDEOUT W      1021    FORES
        MANUAL OPERATION MISSING
        CAUSE:      Plastic ring is missing around metal for
        slide out manual operation
        CORRECTION: Will need one dont have any on hand
        REQUEST:    .1

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
1 WARR  MANUFACTURER WARRANTY JL W-1021  0.50  140.00  70.00
2 WARR  MANUFACTURER WARRANTY JL W-1021  0.28  140.00  39.20
3 WARR  MANUFACTURER WARRANTY JL W-1021  0.39  140.00  54.60
4 WARR  MANUFACTURER WARRANTY JL W-1021  0.50  140.00  70.00
5 WARR  MANUFACTURER WARRANTY JL W-1021  0.50  140.00  70.00
6 WARR  MANUFACTURER WARRANTY JL W-1021  0.50  140.00  70.00
7 WARR  MANUFACTURER WARRANTY JL W-1021  0.50  140.00  70.00
2 WARR  MANUFACTURER WARRANTY JL W-1021  0.17  140.00  23.80
2 WARR  MANUFACTURER WARRANTY JL W-1021  0.05  140.00  7.00
3 WARR  MANUFACTURER WARRANTY JL W-1021  0.07  140.00  9.80
3 WARR  MANUFACTURER WARRANTY JL W-1021  0.04  140.00  5.60
1 RV3F-1  AWNING INSTALL RVDA AW W-1021  0.00  140.00  0.00

```

```

*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
1 SSE  SHOP SUPPLIES - EXTERNAL W-1021  1.00  0.00  0.00

```

```

*****
BILLINGS SUMMARY
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
W 1021  0.00  490.00  0.00  0.00  0.00  490.00
Totals  0.00  490.00  0.00  0.00  0.00  490.00

```

Continued on page 3

Work Order : 13715

&k2S
&k0S