

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13642B

Date In:	22 JUN 26	Author:	MGRAY
Promised Date:	15 JUL 26	Stock No:	11636
:	:	Year:	2027
Customer Name:	62423 - MEYER, BETTY	Manufacturer:	FOREST RIVER
Address:	2122 WOODLAND TRAIL	Brand:	PUMA CAMPING EDITION
:	REEDSBURG, WI	Model:	16DSCE
Postal/Zip:	53959	Miles/Hrs:	0
Phone#(res):	608-225-0137	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	:	Tag#:	**need update on warr0
Purchased Date:	14 APR 26	:	:
Delivery Date:	15 JUL 26	:	:
InService Date:	:	:	:
Serial#:	5ZT2PUEC3V4028310	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - Exterior slide room W    1021    FORES
        has missing sealant
        CAUSE:      Sealant gaps
        CORRECTION: Cleaned areas then used clear silicone
                   to seal   REQUEST: .1
WARR    COMPLAINT:  WARRANTY REPAIR 2 - Many smudges on bath W    1021    FORES
        door
        CAUSE:      Scuffs and scratches
        CORRECTION: I used thick murpheys oil soap to remove
                   the scuffs then a wood marker to cover
                   the scratches REQUEST: .2
WARR    COMPLAINT:  WARRANTY REPAIR 3 - The refrigerator is W    1021    FORES
        very loud it rattles very loudly
        CAUSE:      Possible the refer was a bit crooked
        CORRECTION: It rattled initially when on then a
                   pushed it a bit and no longer rattled so
                   took it out . Brought unit back in
                   turned refer on and it has not made any
                   noise besides normal refer running noise
                   . I WOULD Just LIKE THIS NOTED WITH MFG
                   IF THIS WOULD BEGIN HAPPENING AGAIN PIC
                   OF REFER AND TAG ATTACHED
WARR    COMPLAINT:  WARRANTY REPAIR 4 - the bathroom mirror W    1021    FORES
        has scratches
        CAUSE:      2 Scratches in mirror PLEASE ORDER THE
                   OVAL MIRROR ABOVE BATHROOM VANITY PICS
                   TAKEN
        CORRECTION: ..... REQUEST: .5
```

Continued on page 2

Work Order : 13642B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 5 -Hot and cold inlets   W    1021    FORES
          to water heater are leaking
          CAUSE:      Mfg did not have the inlets in back of
                      water heater tight
          CORRECTION: Tried tightening the ends that thread
                      onto outlet on rear of water heater not
                      helping drained water heater then used
                      socket to tighten cold and hot inlets
                      reinstalled the ends that attach to
                      outlets on rear of water heater filled
                      heater again no leaks heated up still
                      not leaking PICS OF TAG ATTACHED
          REQUEST: .5

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD  W-1021    0.50  140.00  70.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD  W-1021    0.50  140.00  70.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD  W-1021    0.50  140.00  70.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD  W-1021    0.50  140.00  70.00
ARR05 Z992      MISC LABOUR CODE (WARR HOD  W-1021    0.50  140.00  70.00

```

```

*****
Job #  Excode   Description  EXTRAS      bill to  Qty  Price  Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL  W-1021    1.00    0.00    0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts  Labour  Sublet  Extras  Tax  Total
*****
W    1021          0.00   350.00    0.00    0.00    0.00   350.00

          Totals      0.00   350.00    0.00    0.00    0.00   350.00

```

&k2S
&k0S