

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13665B

Date In:	07 JUL 26	Author:	MGRAY
Promised Date:	31 DEC 26	Stock No:	11669
:	:	Year:	2026
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	PUMA DESTINATION
:	CHICAGO, IL	Model:	403LFT
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	06 JUL 26	:	:
Delivery Date:	08 JUL 26	:	:
InService Date:	:	:	:
Serial#:	4X4TPUS2XTP109182	:	:

```
*****
Job #   Description      JOB INFORMATION      Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 -doorside loveseat the W    1021    FORES
        CAUSE:      Came out of floor
        CORRECTION:  Screwed brackets back into floor both
                   sides REQUEST:.2
WARR    COMPLAINT:  WARRANTY REPAIR 2 - rear door side          W    1021    FORES
        CAUSE:      The silicone at the top of the ds
                   bedroom window next to the door had a
                   gap in it and was allowing water to flow
                   in, I put water on top and it would just
                   seep in, I put a new bead of silicone
                   over the gap.
        CORRECTION:  Done REQUEST: .4
WARR    COMPLAINT:  WARRANTY REPAIR 5 - Silicone is smeared W    1021    FORES
        CAUSE:      Several windows had silicone on them, I
                   used quick-solv and window cleaner to
                   get it off
        CORRECTION:  Done REQUEST: .5
WARR    COMPLAINT:  WARRANTY REPAIR 6 -silicone is no longer W    1021    FORES
        CAUSE:      Silicone was no longer protecting behind
                   the screw track, I put a fresh bead of
```

Continued on page 2

Work Order : 13665B

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
              silicone over the exposed area
CORRECTION: Done  REQUEST:.2

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD  W-1021    0.50  140.00  70.00
ARR02 Z992      MISC LABOUR CODE (WARR EG   W-1021    0.13  140.00  18.20
ARR02 Z992      MISC LABOUR CODE (WARR EG   W-1021    0.01  140.00   1.40
ARR02 Z992      MISC LABOUR CODE (WARR EG   W-1021    0.36  140.00  50.40
ARR05 Z992      MISC LABOUR CODE (WARR EG   W-1021    0.50  140.00  70.00
ARR06 Z992      MISC LABOUR CODE (WARR EG   W-1021    0.50  140.00  70.00

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1021          0.00      280.00          0.00          0.00          0.00      280.00

      Totals          0.00      280.00          0.00          0.00          0.00      280.00

```

&k2S
&k0S