

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13524B

Date In:	26 JUN 26	Author:	MGRAY
Promised Date:	26 JUN 26	Stock No:	11046
:	:	Year:	2024
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	FLAGSTAFF CLASSIC TT
:	CHICAGO, IL	Model:	826BHS
Postal/Zip:	60673-1218	Miles/Hrs:	:
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DROPPING 6/19
Purchased Date:	20 APR 26	:	:
Delivery Date:	05 MAY 26	:	:
InService Date:	:	:	:
Serial#:	4X4TFLF27R1906055	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT:	WARRANTY REPAIR 1 - FUSE BOX PANEL BY THE ENTRY DOOR. BOTH BRACKETS ARE BROKEN OFF. CHECK FOR REPAIR.	W	1021 FORES
	CAUSE:	Fuse box by entry door is broken feels like something is pushing on the back of the fuse box and the sliding door hitting it which caused the fuse box to break		
	CORRECTION:	Will need a new fuse box in order to fix it REQUEST: 2hr Plus .5 to make brcket to stop door from redamaging fuse box.		

Job#	Lab Code	Description	LABOUR	Mech Bill to	Hrs	Rate	Total
ARR01	Z992	MISC LABOUR CODE (WARR JL	W-1021	0.50	140.00	70.00	

BILLINGS SUMMARY							
Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	1021	0.00	70.00	0.00	0.00	0.00	70.00
	Totals	0.00	70.00	0.00	0.00	0.00	70.00

&k2S

Continued on page 2

Work Order : 13524B

&k0S