



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$283.23

RO# : 41034 Tag# : T8920585

Check-in: Wed Jun 24, 2026 | 10:51 AM
Ready for Pickup: Wed Jul 15, 2026 | 10:02 AM
Promise Time: Mon Jun 29, 2026 | 6:00 PM

Customer
Henry Grandys
7158178525
+1 - (715) 817 - 8525
Spotakiss618@gmail.com
618 CLOUGH AVE
SUPERIOR, WI 54880

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATG1XT8920585
2 Mi In
In Service Date:
01/01/2017
Sold Date: 04/30/2026
Stock #: KS26-37

Service Advisor
KEVIN GOODIEL
goodielk

A. SC	SERVICE CALL 2105 GULFCOURSE RD BARNES	Customer Pay	\$175.00
-------	---	--------------	----------

Job added by KEVIN GOODIEL on Wed Jun 24, 2026 | 10:51 AM

Op.1 SC -SERVICE CALL

Labor Sale: \$175.00

Labor Cost: \$19.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
boiem	-	0.49	1	1	\$175.00	\$19.00

1. SERVICE CALL

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
\$175.00	\$19.00	\$0.00	\$0.00

B. MISCELLANEOUS	CUSTOMER STATES THE STRING ON THE BLIND BROKE AND NEEDS TO BE RESTRUNG	Warranty Pay	\$0.00
------------------	---	--------------	--------

Job added by KEVIN GOODIEL on Wed Jun 24, 2026 | 10:51 AM

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
boiem	-	0.25	0	0	\$0.00	\$0.00

1. Hold the blind off and found out that the new style blinds are not able to be restrung. They are all glued together and would snap if I tried to break it open needs a new blind took pictures of the tagREQUESTING .30 HR





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$283.23

RO# : 41034 Tag# : T8920585

Check-in: Wed Jun 24, 2026 | 10:51 AM
Ready for Pickup: Wed Jul 15, 2026 | 10:02 AM
Promise Time: Mon Jun 29, 2026 | 6:00 PM

Customer Henry Grandys 7158178525 +1 - (715) 817 - 8525	Billing-Customer Same as Customer	Vehicle 2026 Keystone ASPEN TRAIL 4YDTATG1XT8920585	Service Advisor KEVIN GOODIEL goodielk
---	---	---	---

Total Labor Sale \$0.00	Total Labor Cost \$0.00	Total Parts Sale \$0.00	Total Parts Cost \$0.00
----------------------------	----------------------------	----------------------------	----------------------------

C. MISCELLANEOUS	CUSTOMER STATES THE FRONT LEFT WINDOW BYE THE BED THE CRANK IS ON BACKWARDS AND WINDOW WONT OPEN	Customer Pay	\$35.00
------------------	--	--------------	---------

Tags: Add-on

Job added by KEVIN GOODIEL on Thu Jul 2, 2026 | 11:49 AM

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$35.00

Labor Cost: \$3.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
boiem	-	0.2	0.2	0.2	\$35.00	\$3.80

1. Customer wanted the latch for the emergency exit to be flipped upside down so it's easier for him to open. Drilled out rivets and flipped latch upside down and re-riveted back to the window frame.

Total Labor Sale \$35.00	Total Labor Cost \$3.80	Total Parts Sale \$0.00	Total Parts Cost \$0.00
-----------------------------	----------------------------	----------------------------	----------------------------

D. MISCELLANEOUS	CUSTOMER STATES ADJUST THE TABLE SO ITS NOT CROOKED THEY SHOULD BE THERE TO SHOW YA	Warranty Pay	\$49.50
------------------	---	--------------	---------

Tags: Add-on

Job added by KEVIN GOODIEL on Fri Jul 3, 2026 | 10:57 AM





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$283.23

RO# : 41034 Tag# : T8920585

Check-in: Wed Jun 24, 2026 | 10:51 AM
Ready for Pickup: Wed Jul 15, 2026 | 10:02 AM
Promise Time: Mon Jun 29, 2026 | 6:00 PM

Customer
Henry Grandys
7158178525
+1 - (715) 817 - 8525

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATG1XT8920585

Service Advisor
KEVIN GOODIEL
goodielk

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50

Labor Cost: \$5.70

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
boiem	-	0.11	0.3	0.3	\$49.50	\$5.70

1. Rear bracket on table was not installed straight with the front bracket so the table was sitting at an angle, took out all the screws adjust a table to where it would sit straight and re-screwed bracket back into the bottom of table
REQUESTING .30 HR

Total Labor Sale
\$49.50

Total Labor Cost
\$5.70

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

Additional Fees	Sale Amount	Cost Amount
SSC - Shop Supply Charges	\$11.55	\$0.00

Category	Sale	Cost
Labor	\$259.50	\$28.50
Parts	\$0.00	\$0.00
Sublet	\$0.00	\$0.00
Sublet Labor	\$0.00	\$0.00
Sublet Parts	\$0.00	\$0.00
Fees	\$11.55	\$0.00
Discounts	\$0.00	-
Tax	\$12.18	-
Deductible	\$0.00	-
Insurance/Warranty	\$0.00	-
Invoice Total	\$283.23	\$28.50





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$283.23

RO# : 41034 Tag# : T8920585

Check-in: Wed Jun 24, 2026 | 10:51 AM
Ready for Pickup: Wed Jul 15, 2026 | 10:02 AM
Promise Time: Mon Jun 29, 2026 | 6:00 PM

Customer
Henry Grandys
7158178525
+1 - (715) 817 - 8525

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATG1XT8920585

Service Advisor
KEVIN GOODIEL
goodielk

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	SC	Wed Jul 8, 2026	12:08 PM	12:37 PM	0.49 hrs	CP	boiem	1 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Wed Jul 8, 2026	12:37 PM	12:52 PM	0.25 hrs	W	boiem	0 hrs
Tag: Regular Hour			Reason: -					
C	MISC	Wed Jul 8, 2026	12:52 PM	1:04 PM	0.20 hrs	CP	boiem	0.2 hrs
Tag: Regular Hour			Reason: -					
D	MISC	Wed Jul 8, 2026	1:04 PM	1:11 PM	0.11 hrs	W	boiem	0.3 hrs
Tag: Regular Hour			Reason: -					

Accounting Info - Customer Pay

GL Account #	Control #	Franchise	Amount
57000	41034	LINK RV	-\$210.00
67000	41034	LINK RV	\$22.80
14400	boiem	LINK RV	-\$22.80
77700	41034	LINK RV	-\$11.55
21500	SALES TAX	LINK RV	-\$11.07
21510	COUNTY TAX	LINK RV	-\$1.11

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
11400	41034	LINK RV	\$49.50
57200	41034	LINK RV	-\$49.50
67200	41034	LINK RV	\$5.70
14400	boiem	LINK RV	-\$5.70

