1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
$1,712.52

RO# : 41132 Tag# : TE760532

Check-in: Tue Jul 7, 2026 | 9:06 AM
Ready for Pickup: Thu Jul 9, 2026 | 1:43 PM
Promise Time: Sun Jul 12, 2026 | 6:00 PM

Customer
Jaime Zar
1247136
+1 - (715) 292 - 8596
zartobejlf@yahoo.com
110 E Tyler Ave
Mellen, WI 54546

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2026 KEYSTONE AVALANCHE 321RL
4YDFAVR2X*TE760532*
2 Mi In
Sold Date: 06/30/2026
Stock #: KS26-41

Service Advisor
KEVIN GOODIEL
goodielk

A. SC — **SERVICE CALL 31561 SACKETT RD MELLEN WI** — **Warranty Pay** — **$990.00**

Job added by KEVIN GOODIEL on Tue Jul 7, 2026 | 9:06 AM

Op.1 SC -SERVICE CALL

Labor Sale: $990.00

Labor Cost: $228.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	6.06	6	6	$990.00	$228.00

1. SERVICE CALL

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
$990.00	$228.00	$0.00	$0.00

B. MISCELLANEOUS — **CUSTOMER STATES THE BATTERYS ARE NOT CHARGING THEY HAVE NO 12 VOLT POWER EVEN WHEN PLUGGED IN** — **Warranty Pay** — **$662.52**

Job added by KEVIN GOODIEL on Tue Jul 7, 2026 | 9:06 AM

1. TO HOT IN CABINET

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: $0.00

Labor Cost: $0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0	0	0	$0.00	$0.00

1. Tested voltage at batteries, they were at 12.6V. Unit was plugged in, so checked and unit had 120V. Went to fuse panel and checked polarity fuses, all 3 were good, but each only had 12.6V, so converter was not working. Removed fuse panel cover and inspected, found the converter is bad and damaged from excess heat. Converter is mounted in a

© Tekion Corp 2026

Customer
Jaime Zar
1247136
+1 - (715) 292 - 8596

Billing-Customer
Same as Customer

Vehicle
2026 KEYSTONE AVALANCHE 321RL
4YDFAVR2X*TE760532*

Service Advisor
KEVIN GOODIEL
goodielk

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: $0.00

Labor Cost: $0.00

cabinet with a cabinet door covering it, but has no air intake vents. Believe converter overheated due to lack of airflow. Took pics of damaged converter and of cabinet it mounts into to show no airflow. REQUESTING 2.0 HR

Parts

Parts Total Sale Amount	$662.52
Parts Total Cost Amount	$509.63

Name	Quantity	Unit Price	Sale Price	Cost Price
ARTWF-9580-MBA - CONV/CHGR-MAIN BRD ASSEMBLY ONLY-80AMP DC OUTPUT	1	$333.87	$333.87	$256.82
03181472 - CONVERTER 65 AMP	1	$328.65	$328.65	$252.81

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
$0.00	$0.00	$662.52	$509.63

C.	**MISCELLANEOUS**	**CUSTOMER STATES THE SHOWER DOORS WERE SHATTERED WHEN THEY GOT TO THERE SITE**	**Warranty Pay**	**$0.00**

Job added by KEVIN GOODIEL on Tue Jul 7, 2026 | 9:06 AM

1. UNKNOWN, DOOR SHATTERED WHILE IN CUSTOMERS HAND WHILE OPEINING

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: $0.00

Labor Cost: $0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0	0	0	$0.00	$0.00

1. CUSTOMERS OPENED DOOR AND IT SHATTERED ON THEM . REQUESTING 2.0 HR

© Tekion Corp 2026

1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
$1,712.52

RO# : 41132 Tag# : TE760532
Check-in: Tue Jul 7, 2026 | 9:06 AM
Ready for Pickup: Thu Jul 9, 2026 | 1:43 PM
Promise Time: Sun Jul 12, 2026 | 6:00 PM

Customer	Billing-Customer	Vehicle	Service Advisor
Jaime Zar 1247136 +1 - (715) 292 - 8596	Same as Customer	**2026 KEYSTONE AVALANCHE 321RL** **4YDFAVR2X*TE760532***	**KEVIN GOODIEL** goodielk

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
$0.00	$0.00	$0.00	$0.00

D.	**MISCELLANEOUS**	**CUSTOMER STATES THE 30 LB PROPANE TANKS WERE EMPTY WHEN THEY RECIEVED IT SWAP OUT TWO TANKS**	**Internal Pay**	**$60.00**

Job added by KEVIN GOODIEL on Tue Jul 7, 2026 | 9:06 AM

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: $60.00

Labor Cost: $19.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0.16	0.5	0.5	$60.00	$19.00

1. Tanks were full, regulator was turned to the middle, so flipped to one side and tested stove top. No issue.

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
$60.00	$19.00	$0.00	$0.00

E.	**MISCELLANEOUS**	**CUSTOMER STATES THAT THE #2 AWNING ROLLS OUT BUT BLEW 3 FUSES TRYING TO BRING IT BACK IN**	**Customer Pay**	**$0.00**

Tags: Add-on

Job added by KEVIN GOODIEL on Wed Jul 8, 2026 | 9:08 AM

© Tekion Corp 2026

1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
$1,712.52

RO# : 41132 Tag# : TE760532

Check-in: Tue Jul 7, 2026 | 9:06 AM
Ready for Pickup: Thu Jul 9, 2026 | 1:43 PM
Promise Time: Sun Jul 12, 2026 | 6:00 PM

Customer
Jaime Zar
1247136
+1 - (715) 292 - 8596

Billing-Customer
Same as Customer

Vehicle
2026 KEYSTONE AVALANCHE 321RL
4YDFAVR2X*TE760532*

Service Advisor
KEVIN GOODIEL
goodielk

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: $0.00
Labor Cost: $0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0	0	0	$0.00	$0.00

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
$0.00	$0.00	$0.00	$0.00

Additional Fees	Sale Amount	Cost Amount
SSC - Shop Supply Charges	$0.00	$0.00

Category	Sale	Cost
Labor	**$1,050.00**	**$247.00**
Parts	**$662.52**	**$509.63**
Sublet	**$0.00**	**$0.00**
Sublet Labor	**$0.00**	**$0.00**
Sublet Parts	**$0.00**	**$0.00**
Fees	**$0.00**	**$0.00**
Discounts	**$0.00**	-
Tax	**$0.00**	-
Deductible	**$0.00**	-
Insurance/Warranty	**$0.00**	-
Invoice Total	**$1,712.52**	**$756.63**

© Tekion Corp 2026

1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
$1,712.52

RO# : 41132 Tag# : TE760532
Check-in: Tue Jul 7, 2026 | 9:06 AM
Ready for Pickup: Thu Jul 9, 2026 | 1:43 PM
Promise Time: Sun Jul 12, 2026 | 6:00 PM

Customer
Jaime Zar
1247136
+1 - (715) 292 - 8596

Billing-Customer
Same as Customer

Vehicle
2026 KEYSTONE AVALANCHE 321RL
4YDFAVR2X*TE760532*

Service Advisor
KEVIN GOODIEL
goodielk

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	SC	Tue Jul 7, 2026	10:43 AM	11:03 AM	0.34 hrs	W	lafavet	6 hrs
Tag: Regular Hour			**Reason:** -					
D	MISC	Tue Jul 7, 2026	11:03 AM	11:13 AM	0.16 hrs	I	lafavet	0.5 hrs
Tag: Regular Hour			**Reason:** -					
A	SC	Tue Jul 7, 2026	11:13 AM	4:56 PM	5.72 hrs	W	lafavet	-
Tag: LOG_OFF			**Reason:** -					
B	MISC	-	-	-	0 hrs	W	lafavet	0 hrs
C	MISC	-	-	-	0 hrs	W	lafavet	0 hrs
E	MISC	-	-	-	0 hrs	CP	lafavet	0 hrs

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
11400	41132	LINK RV	$1,652.52
57200	41132	LINK RV	-$990.00
67200	41132	LINK RV	$228.00
14400	lafavet	LINK RV	-$228.00
54200	41132	LINK RV	-$662.52
64000	41132	LINK RV	$509.63
14000	41132	LINK RV	-$509.63

Accounting Info - Internal

GL Account #	Control #	Franchise	Amount
14300	KS26-41	LINK RV	$60.00
57300	41132	LINK RV	-$60.00

© Tekion Corp 2026

1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
$1,712.52

RO# : 41132 Tag# : TE760532

Check-in: Tue Jul 7, 2026 | 9:06 AM
Ready for Pickup: Thu Jul 9, 2026 | 1:43 PM
Promise Time: Sun Jul 12, 2026 | 6:00 PM

Customer
Jaime Zar
1247136
+1 - (715) 292 - 8596

Billing-Customer
Same as Customer

Vehicle
2026 KEYSTONE AVALANCHE 321RL
4YDFAVR2X *TE760532*

Service Advisor
KEVIN GOODIEL
goodielk

Accounting Info - Internal

GL Account #	Control #	Franchise	Amount
67300	41132	LINK RV	$19.00
14400	lafavet	LINK RV	-$19.00

© Tekion Corp 2026