1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
$760.45

RO# : 41018 Tag# : N17V3007

Check-in: Mon Jun 22, 2026 | 8:16 AM
Ready for Pickup: Fri Jun 26, 2026 | 2:08 PM
Promise Time: Sat Jun 27, 2026 | 6:00 PM

Customer
Joseph Montano
1237752
+1 - (715) 292 - 7369
jdmontano87@gmail.com
37375 Community Rd unit 20
Red Cliff, WI 54814

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2022 Jayco Jyflslx
1UJBJ0BN7*N17V3007*
1 Mi In / 1 Mi Out
Sold Date: 08/15/2024
Stock #: 22-128

Service Advisor
BONNIE SEEMANN
bonnie

A.	**MISCELLANEOUS**	**CUSTOMER STATES THERES A SHORT GOING TO OUT DOOR LIGHT IT TRIPS IF THE INSIDE LIGHTS ARE ON AT THE SAME TIME**	**Warranty Pay**	**$49.50**

Job added by KEVIN GOODIEL on Mon Jun 22, 2026 | 8:16 AM

1. Bad connection behind switch

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: $49.50

Labor Cost: $7.20

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.28	0.3	0.3	$49.50	$7.20

1. Bad switch, recommend new. Request 2 hours. Switch was taped off to prohibit use. Turned both lights on. Outside light appeared to short. Removed switch, inspected wires, tested for power, tested switch for function. Cleaned connection points, reinstalled switch, Shook camper and tapped around switch and lights, removed tape, left lights on for duration of total work, no short or fault detected. Cleaned up area, wrote report. Works as it should.

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
$49.50	$7.20	$0.00	$0.00

B.	**MISCELLANEOUS**	**CUSTOMER STATES THE LIGHT BY THE BED WORKS SOMETIMES BUT NOT ALL THE TIME**	**Warranty Pay**	**$82.50**

Job added by KEVIN GOODIEL on Mon Jun 22, 2026 | 8:16 AM

1. Concern of short/fault

© Tekion Corp 2026

1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
$760.45

RO# : 41018 Tag# : N17V3007

Check-in: Mon Jun 22, 2026 | 8:16 AM
Ready for Pickup: Fri Jun 26, 2026 | 2:08 PM
Promise Time: Sat Jun 27, 2026 | 6:00 PM

Customer	Billing-Customer	Vehicle	Service Advisor
Joseph Montano	Same as Customer	**2022 Jayco Jyflslx**	**BONNIE SEEMANN**
1237752		**1UJBJ0BN7*N17V3007***	bonnie
+1 - (715) 292 - 7369			

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: $82.50

Labor Cost: $12.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.17	0.5	0.5	$82.50	$12.00

1. Request 1.0 hour: Turned on all lights in bedroom, flicked buttons to test switches,rattled headrest and surrounding areas that had 12v wiring connections in the area, left lights on for the duration of work while addressing other issues. Could not duplicate issue.

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
$82.50	$12.00	$0.00	$0.00

C.	**MISCELLANEOUS**	**CUSTOMER STATES BLACK TANK FLUSH LEAKS ON THE INSIDE. ***IT LEAKS UNDER THE BATHROOM SINK WHEN TURN ON THE WATER, WHEN THE BLACK TANK SPRAYER IS BEING USED.***	**Warranty Pay**	**$235.68**

Job added by KEVIN GOODIEL on Mon Jun 22, 2026 | 8:16 AM

1. Concern

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: $231.00

Labor Cost: $33.60

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	1.29	1.4	1.4	$231.00	$33.60

1. Replace black tank valve? 4 hours requested: Retrieved lift, lifted unit, inspected externally, hooked water, flushed toilet, Tested cables, cut access hole to inspect further, inspected further, found no evidence of internal leaks, waste gate remained dry during function test, however there was some waste caught between the waste gate and exit cap. Exit cap held minute amount from me testing, would usually have some amount just from settling and condensation, which is normal, found no issues with function of waste gate.

© Tekion Corp 2026

1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
$760.45

RO# : 41018 Tag# : N17V3007
Check-in: Mon Jun 22, 2026 | 8:16 AM
Ready for Pickup: Fri Jun 26, 2026 | 2:08 PM
Promise Time: Sat Jun 27, 2026 | 6:00 PM

Customer	Billing-Customer	Vehicle	Service Advisor
Joseph Montano	Same as Customer	**2022 Jayco JyflsIx**	**BONNIE SEEMANN**
1237752		**1UJBJ0BN7*N17V3007***	bonnie
+1 - (715) 292 - 7369			

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: $231.00

Labor Cost: $33.60

Parts

Parts Total Sale Amount	$4.68
Parts Total Cost Amount	$3.60

Name	Quantity	Unit Price	Sale Price	Cost Price
08011439 - SEAL,BLACK PER FT	3	$1.56	$4.68	$3.60

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
$231.00	$33.60	$4.68	$3.60

D.	**MISCELLANEOUS**	**CUSTOMER STATES HE NOTICED PINK(ANTI FREEZE) BACK BEHIND WATER HEATER**	**Warranty Pay**	**$165.00**

Job added by KEVIN GOODIEL on Mon Jun 22, 2026 | 8:16 AM

1. Loose connection at cold water intake

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: $165.00

Labor Cost: $24.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.29	1	1	$165.00	$24.00

1. request 2.0 hours: Removed cover, confirmed evidence of leak via water marks on back of luan board as well as pinbk around cold water intake. Tightened cold water intake, checked hot water outlet, pressure tested for leaks,no leaks detected,reassembled cover, wrapped up hose. Wrote report.

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
$165.00	$24.00	$0.00	$0.00

E.	**ANNUAL**	**ANNUAL INSPECTION**	**Customer Pay**	**$175.00**

© Tekion Corp 2026

1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
$760.45

RO# : 41018 Tag# : N17V3007

Check-in: Mon Jun 22, 2026 | 8:16 AM
Ready for Pickup: Fri Jun 26, 2026 | 2:08 PM
Promise Time: Sat Jun 27, 2026 | 6:00 PM

Customer	Billing-Customer	Vehicle	Service Advisor
Joseph Montano	Same as Customer	**2022 Jayco Jyflslx**	**BONNIE SEEMANN**
1237752		**1UJBJ0BN7*N17V3007***	bonnie
+1 - (715) 292 - 7369			

Job added by KEVIN GOODIEL on Mon Jun 22, 2026 | 8:16 AM

1. ANNUAL

Op.1 ANNUAL -ANNUAL INSPECTION

Labor Sale: $175.00

Labor Cost: $24.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.58	1	1	$175.00	$24.00

1. ANNUAL INPECTION: Needed quad sealant on one corner and various small spots to seal on roof. Cleaned AC filter, cleaned combustion chambers and housing areas on water heater, furnace and fridge,

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
$175.00	$24.00	$0.00	$0.00

F.	**MISCELLANEOUS**	**CUSTOMER STATES THE OUTSIDE COVER FOR THE TV HOOKUP DOESN'T STAY SHUT. ***CUSTOMER STATES IT FLOPS UP & DOWN WHEN GOING DOWN THE ROAD.*** **	**Warranty Pay**	**$33.00**

Tags: Add-on

Job added by BONNIE SEEMANN on Mon Jun 22, 2026 | 8:23 AM

1. Concern

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: $33.00

Labor Cost: $4.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.13	0.2	0.2	$33.00	$4.80

1. Request 1.0 hours to replace and seal cover; Llocated both cable ports. Inspected both of them. Found nothing wrong. Walked over to 3 other Jayce units to inspect port covers for function and disparities. None of them locked, just shut. As far as I can tell, it works as it should.

© Tekion Corp 2026

1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
$760.45

RO# : 41018 Tag# : N17V3007

Check-in: Mon Jun 22, 2026 | 8:16 AM
Ready for Pickup: Fri Jun 26, 2026 | 2:08 PM
Promise Time: Sat Jun 27, 2026 | 6:00 PM

Customer
Joseph Montano
1237752
+1 - (715) 292 - 7369

Billing-Customer
Same as Customer

Vehicle
2022 Jayco Jyflslx
1UJBJ0BN7*N17V3007*

Service Advisor
BONNIE SEEMANN
bonnie

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
$33.00	$4.80	$0.00	$0.00

Additional Fees	Sale Amount	Cost Amount
SSC - Shop Supply Charges	$9.62	$0.00

Category	Sale	Cost
Labor	**$736.00**	**$105.60**
Parts	**$4.68**	**$3.60**
Sublet	**$0.00**	**$0.00**
Sublet Labor	**$0.00**	**$0.00**
Sublet Parts	**$0.00**	**$0.00**
Fees	**$9.62**	**$0.00**
Discounts	**$0.00**	-
Tax	**$10.15**	-
Deductible	**$0.00**	-
Insurance/Warranty	**$0.00**	-
Invoice Total	**$760.45**	**$109.20**

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
E	ANNUAL	Mon Jun 22, 2026	10:48 AM	10:56 AM	0.13 hrs	CP	matthewl	1 hrs
Tag: Regular Hour			**Reason:** -					
E	ANNUAL	Mon Jun 22, 2026	11:03 AM	11:30 AM	0.45 hrs	CP	matthewl	-
Tag: Regular Hour			**Reason:** -					

© Tekion Corp 2026

1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
$760.45

RO# : 41018 Tag# : N17V3007

Check-in: Mon Jun 22, 2026 | 8:16 AM
Ready for Pickup: Fri Jun 26, 2026 | 2:08 PM
Promise Time: Sat Jun 27, 2026 | 6:00 PM

Customer
Joseph Montano
1237752
+1 - (715) 292 - 7369

Billing-Customer
Same as Customer

Vehicle
2022 Jayco JyflsIx
1UJBJ0BN7*N17V3007*

Service Advisor
BONNIE SEEMANN
bonnie

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
F	MISC	Mon Jun 22, 2026	12:11 PM	12:19 PM	0.13 hrs	W	matthewl	0.2 hrs
Tag: Regular Hour			**Reason:** -					
A	MISC	Mon Jun 22, 2026	12:19 PM	12:36 PM	0.28 hrs	W	matthewl	0.3 hrs
Tag: Regular Hour			**Reason:** -					
B	MISC	Mon Jun 22, 2026	12:36 PM	12:47 PM	0.17 hrs	W	matthewl	0.5 hrs
Tag: Regular Hour			**Reason:** -					
D	MISC	Mon Jun 22, 2026	12:47 PM	1:04 PM	0.29 hrs	W	matthewl	1 hrs
Tag: Regular Hour			**Reason:** -					
C	MISC	Mon Jun 22, 2026	1:07 PM	1:53 PM	0.76 hrs	W	matthewl	1.4 hrs
Tag: Regular Hour			**Reason:** -					
C	MISC	Mon Jun 22, 2026	1:54 PM	2:25 PM	0.53 hrs	W	matthewl	-
Tag: Regular Hour			**Reason:** -					

Accounting Info - Customer Pay

GL Account #	Control #	Franchise	Amount
57000	41018	LINK RV	-$175.00
67000	41018	LINK RV	$24.00
14400	matthewl	LINK RV	-$24.00
77700	41018	LINK RV	-$9.62
21500	SALES TAX	LINK RV	-$9.23
21510	COUNTY TAX	LINK RV	-$0.92

© Tekion Corp 2026

1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
$760.45

RO# : 41018 Tag# : N17V3007

Check-in: Mon Jun 22, 2026 | 8:16 AM
Ready for Pickup: Fri Jun 26, 2026 | 2:08 PM
Promise Time: Sat Jun 27, 2026 | 6:00 PM

Customer
Joseph Montano
1237752
+1 - (715) 292 - 7369

Billing-Customer
Same as Customer

Vehicle
2022 Jayco JyflsIx
1UJBJ0BN7*N17V3007*

Service Advisor
BONNIE SEEMANN
bonnie

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
11400	41018	LINK RV	$565.68
57200	41018	LINK RV	-$561.00
67200	41018	LINK RV	$81.60
14400	matthewl	LINK RV	-$81.60
54200	41018	LINK RV	-$4.68
64000	41018	LINK RV	$3.60
14000	41018	LINK RV	-$3.60

© Tekion Corp 2026