



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$341.69

RO# : 41064 Tag# : T8920353

Check-in: Mon Jun 29, 2026 | 9:13 AM
Ready for Pickup: Tue Jun 30, 2026 | 10:03 AM
Promise Time: Sat Jul 4, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222
NO@GMAIL.COM
1025 WI-77
Minong, WI 54859

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATL22 T8920353
1 Mi In / 1 Mi Out
Stock #: KS26-09

Service Advisor
BONNIE SEEMANN
bonnie

A. MISCELLANEOUS	DEALER STATES THE TOILET IS LEAKING.	Warranty Pay	\$209.69
-------------------------	---	---------------------	-----------------

Job added by BONNIE SEEMANN on Mon Jun 29, 2026 | 9:13 AM

1. Valve was bad

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$198.00

Labor Cost: \$28.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	1.03	1.2	1.2	\$198.00	\$28.80

1. replaced valve. Tested. Works. No leaks.

Parts

Parts Total Sale Amount \$11.69

Parts Total Cost Amount \$8.99

Name	Quantity	Unit Price	Sale Price	Cost Price
SFRTK-017 - SEAFLO RV Toilet 90° Angled Water Inlet Valve Kit	1	\$11.69	\$11.69	\$8.99

Total Labor Sale
\$198.00

Total Labor Cost
\$28.80

Total Parts Sale
\$11.69

Total Parts Cost
\$8.99

B. MISCELLANEOUS	DEALER STATES SIDE OF DINETTE CAME OFF	Warranty Pay	\$132.00
-------------------------	---	---------------------	-----------------

Tags: [Add-on](#)





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$341.69

RO# : 41064 Tag# : T8920353

Check-in: Mon Jun 29, 2026 | 9:13 AM
Ready for Pickup: Tue Jun 30, 2026 | 10:03 AM
Promise Time: Sat Jul 4, 2026 | 6:00 PM

Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 Keystone ASPEN TRAIL 4YDTATL22 T8920353	Service Advisor BONNIE SEEMANN bonnie
---	---	--	--

Job added by CODY EAGLE on Mon Jun 29, 2026 | 3:31 PM

1. Shallow screws

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$132.00

Labor Cost: \$19.20

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.81	0.8	0.8	\$132.00	\$19.20

1. There was 2 screws to wall (no anchor) that were reamed out. 2 screws from inside to frame had approximately only 1/4" of grab due to angle of screws. Put wood putty in old screw holes to hold old screws in as hole covers and added 2 screws for structural integrity. Applied extra reinforcement via brad nails to replace shallow penetrating screws and extra support to critical support joints.

Total Labor Sale
\$132.00

Total Labor Cost
\$19.20

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

Category	Sale	Cost
Labor	\$330.00	\$48.00
Parts	\$11.69	\$8.99
Sublet	\$0.00	\$0.00
Sublet Labor	\$0.00	\$0.00
Sublet Parts	\$0.00	\$0.00
Fees	\$0.00	\$0.00
Discounts	\$0.00	-
Tax	\$0.00	-
Deductible	\$0.00	-
Insurance/Warranty	\$0.00	-
Invoice Total	\$341.69	\$56.99





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$341.69

RO# : 41064 Tag# : T8920353

Check-in: Mon Jun 29, 2026 | 9:13 AM
Ready for Pickup: Tue Jun 30, 2026 | 10:03 AM
Promise Time: Sat Jul 4, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATL22 T8920353

Service Advisor
BONNIE SEEMANN
bonnie

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Mon Jun 29, 2026	2:44 PM	3:45 PM	1.03 hrs	W	matthewl	1.2 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Mon Jun 29, 2026	3:49 PM	4:32 PM	0.72 hrs	W	matthewl	0.8 hrs
Tag: Regular Hour			Reason: Employee shift is ended					
B	MISC	Tue Jun 30, 2026	8:08 AM	8:13 AM	0.09 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
11400	41064	LINK RV	\$341.69
57200	41064	LINK RV	-\$330.00
67200	41064	LINK RV	\$48.00
14400	matthewl	LINK RV	-\$48.00
54200	41064	LINK RV	-\$11.69
64000	41064	LINK RV	\$8.99
14000	41064	LINK RV	-\$8.99

