

Pre-Authorization

Pre-Authorization number PA03080494 Reference no: 66842 Status: Approved Approved by kiddz Approved date 3/28/2022
 Servicing Name Address VIN Retail sold on Dealer

1194 Basden's American RV Basden's American RV 4YDTCGR20NV506310
 600 E Baseline Rd
 Evansville, IN 47725

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	1200603A	Crossmember, W	0.00	0.70	0.50		1	0.50	Complaint:FRONT BATTERY FRAME THE WELDS ARE BROKEN Cause:FOUND BATTERY FRAME BUSTED Correction:SANDED OFF,REWELDED AND PAINTED. KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.
2	3304508B	Shade - Pleated -	0.00	0.70	0.20		1	0.20	Complaint:FRONT BED ROOM SHADE HAS HOLES IN IT (NOD) Cause:FOUND SHADE HAS HOLE IN IT AND ITS DAMAGED Correction:REPLACE THE SHADE KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual
					0.70				

Pre-Authorization number PA03080494

For paper claims only use one pre-authorization number per warranty claim for

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company