

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 13752

|                 |                     |                 |                  |
|-----------------|---------------------|-----------------|------------------|
| Date In:        | 03 JUL 26           | Author:         | CPEARSON         |
| Promised Date:  | 29 JUL 26           | Stock No:       | 11339            |
| :               |                     | Year:           | 2025             |
| Customer Name:  | 1020 - GRAND DESIGN | Manufacturer:   | GRAND DESIGN     |
| Address:        | 11333 COUNTY RD 2   | Brand:          | INFLUENCE        |
| :               | MIDDLEBURY, IN      | Model:          | 3203GK           |
| Postal/Zip:     | 46540               | Miles/Hrs:      | 0                |
| Phone#(res):    | 888-825-2820        | Exterior Color: |                  |
| Phone#(bus):    |                     | Unit Type:      | FW-FIFTH WHEEL   |
| Cell Phone:     |                     | License#:       |                  |
| Email:          | NONE                | Tag#:           | ST+PU 7/29 @ 2PM |
| Purchased Date: | 03 JUL 26           | :               |                  |
| Delivery Date:  | 29 JUL 26           | :               |                  |
| InService Date: |                     | :               |                  |
| Serial#:        | 573FS3725SAA21223   | :               |                  |

```
*****
Job #  Description                      JOB INFORMATION                      Type Bill To
*****
1      MONTHLY SPECIAL                      I      DO      DEALE
2      TOW:  BC:  YN TP:  YN HITCH:          I      DO      DEALE
3      2ND LITHIUM BATTERY                  I      DO      DEALE
4      SCREEN DOOR CROSS BAR 014717421867    I      DO      DEALE
5      SECURE TRIM ON LEFT HAND SIDE OF FIRE PLACE  I      DO      DEALE
6      COMPLAINT:  DOORS ABOVE STOVE NEED ADJUSTMENT  I      DO      DEALE
           HITTING
           CAUSE:      Misaligned doors
           CORRECTION: Adjusted the hinges
7      CAPTURE PLATE 8219.1723-----331723---DAVE ORDERED  I      DO      DEALE
           ALREADY
CEN    CLEAN EXTERIOR- NEW                  I      PDI     PRE-D
CIN    CLEAN INTERIOR- NEW                  I      PDI     PRE-D
ST     SHOWTHRU&SHOWOUT SALESMAN: DAKOTA    I      PDI     PRE-D
WARR   COMPLAINT:  WARRANTY REPAIR 1 -slide rooms are not  W      1020    GRAND
           coming out
           CAUSE:      Check slide outs for operation. Slides
           will work going in, but not out.
           Bypassed unity boar, then manually
           hooked up to battery direct, then they
           would go out. Tried a hard reset, but
           that did not work. Need new unity board.
           Pics uploaded.
           CORRECTION: Installed new unity board. Tested good
8      COMPLAINT:  FRONT ENTRY DOOR HARD TO OPEN          I      PDI     PRE-D
           CAUSE:      Entrance door is hard to open.
           CORRECTION: Adjusted steps down to the proper height
           for door to clear. Then lubricated
```

Continued on page 2

Work Order : 13752

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
          latch. Tested good.
9      COMPLAINT:  THE DS SLIDEOUT REAR INTERIOR FACIA HITS W      1020    GRAND
          PANTRY AND CABINET DOOR WHEN COMING IN
          OR OUT.
          CAUSE:    Ds slide rear facia hits rear cabinet
          door handles when going in and out
          CORRECTION: Adjusted slide mechanism for more
          clearance of the rear cabinet. Tested
          good.
SUM     SUMMERIZE CAMPER AND DEWINTERIZE                I      PDI      PRE-D
PDIF    SOLD FINISH PREP (NEW FIFTH WHEEL)              E      41484    KRAM
ISRO    INTERNAL STOCK REPAIR 01. Assisting HEATHER WITH  E      41484    KRAM
          CEPTURE PLATE SHE NOR I. HAVE ASSEMBLED ONE BEFORE

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
CIN    019079236326 TOILET TISSUE, SGL. 2 PL I-PDI          1        1.69        1.69
CIN    014717396042 HTS STANDARD 10' SEWER H I-PDI          1        5.89        5.89
CIN    019079900142 PARK ADAPTER BULK 30-15 I-PDI          1        2.33        2.33
7      816456012029 CAPTURE PLATE RHINO PINB I-DO          1       141.41       141.41
WARRO  822050305    MONITOR PANEL DIMMING CO W-1020        1       505.08       505.08
CIN    093344312410 ADAPTER 30 AMP MALE TO 5 I-PDI          1        17.20        17.20
4      014717421867 RV SCREEN DOOR CROSS BAR I-DO          1        16.22        16.22
PDIFW  RS1275       12v 75ah LiFePo4 Lithium E-41484        0       157.25        0.00

```

```

*****
Job# Lab Code Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
  3 Z990      MISC LABOUR CODE (EXTE EG    I-DO          0.39      70.00      27.30
CEN CE      CLEAN EXTERIOR                I-PDI          0.00      70.00        0.00
CIN CI      CLEAN INTERIOR                I-PDI          0.00      70.00        0.00
ST RV1D-3    SHOW THRU & PICK UP PD        I-PDI          0.00      70.00        0.00
  7 Z990      MISC LABOUR CODE (EXTE HOD    I-DO          0.00      70.00        0.00
  6 Z990      MISC LABOUR CODE (EXTE HOD    I-DO          0.00      70.00        0.00
  5 Z990      MISC LABOUR CODE (EXTE EG     I-DO          0.50      70.00       35.00
  4 Z990      MISC LABOUR CODE (EXTE EG     I-DO          0.50      70.00       35.00
  6 Z990      MISC LABOUR CODE (EXTE HOD    I-DO          0.50      70.00       35.00
  3 Z990      MISC LABOUR CODE (EXTE HOD    I-DO          0.11      70.00        7.70
ARR01 DIAG    DIAGNOSTICS                    TD      W-1020        0.50     140.00       70.00
ARR01 R555    INTERFACE BOARD, R & R        TD      W-1020        1.00     140.00      140.00
  8 WARR      MANUFACTURER WARRANTY         TD      I-PDI          0.50      70.00       35.00
  9 DIAG      DIAGNOSTICS                    TD      W-1020        0.50     140.00       70.00
  9 RV29A-3    SLIDE OUT ROOM HEIGHTS        TD      W-1020        1.00     140.00      140.00
  8 DIAG      DIAGNOSTICS                    I-PDI          0.00      70.00        0.00
SUM SUMM      SUMMERIZE - FLUSH ANTI        HOD      I-PDI          0.50      70.00       35.00
DIFWN RV1F-3B SOLD FINISH                    HOD      E-41484        0.00     130.00        0.00
DIFWN RV1F-3B SOLD FINISH                    HOD      E-41484        0.38     130.00       49.40
ISR01 Z991    MISC LABOUR CODE (INTE JL     E-41484        0.00     130.00        0.00

```

Continued on page 3

Work Order : 13752

```

*****
Job #  Excode   Description   EXTRAS      bill to    Qty    Price    Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL  W-1020    1.00    3.71     3.71
ARR01  FRT      FREIGHT                W-1020    0.00    0.00     0.00
DIFWN  LP        PROPANE                E-41484   0.00    0.00     0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
E      41484        0.00     49.40     0.00     0.00     2.72     52.12
I      DO          157.63    140.00     0.00     0.00     0.00    297.63
I      PDI          27.11     70.00     0.00     0.00     0.00     97.11
W      1020         505.08    420.00     0.00     3.71     0.00    928.79

Totals          689.82    679.40     0.00     3.71     2.72    1,375.65

```