BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 79109
MANUFACTURER'S CLAIM #:

Manufacturer: 52215 - ALLIANCE RV, LLC
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11723 - 2026 VALOR 35A14 7M5FV3922TD401205
VIN: 7M5FV3922TD401205 HIN: SER#: 7M5FV3922TD401205
Mileage: 0 Work Order Comp: 14 AUG 26
Auth. No: Dealer #:
Warr. Date: Work Order Date: 24 FEB 26 Inv #: 433846

WO #	Job #	Description	JOB INFORMATION
79109	2	DENT IN REAR BATHROOM WINDOW	Dent in window. During pdi noticed the rear bathroom window had a dent on the interior side. Pictures taken. Parts request submitted
79109	3	CABINET DOOR IS DAMAGED + GLASS IS FALLING OUT	Cabinet door During pdi noticed the cabinet door was damanged and the glass was falling out of the door. Pictures taken. Parts request submitted
79109	4	FOLDING TABLE DAMAGED	Folding table. During pdi noticed folding table in garage had a dent and scratch on the wood of table. Pictures taken. Parts request submitted
79109	8	GLASS CHIPPED IN BED ROOM CLOSET DOOR	Bedroom door glass During pdi noticed the glass in the bedroom door was chipped. Pictures taken. Parts request submitted
79109	9	BED ROOM DRAWER IS SCRATCHED UP	Bedroom drawer During pdi noticed the bedroom drawer had lots or scratches on in. Pictures taken. Parts reqeust submitted

Claim : 79109

WO #	Job #	Description	JOB INFORMATION
79109	12	SCRATCH ON NOSE DOCKING LIGHT	Nose light During pdi noticed a scratch on a docking light on nose of camper. Pictures taken. Partd request submitted
79109	14	THE COLOR OF THE SPEAKERS INSIDE LIVING ROOM HAVE DISCOLORED	Living room speaker During pdi noticed the living room speaker had become discolored. Tried cleaning off speaker but nothing cleaned discoloration. Parts request submitted for new speaker
79109	15	THERE IS NO RECEPTION AT THE TELEVISION	No reception at tv During pdi while trying to get reception at tv no channels would come through. Booster is turned on but no channels would come through. Connected test tv to booster. And picture and sound came through. Connected tv to cable connection in bedroom. Picture and sound came through. Connected test tv to cable connection on both ends in livingroom and no picture or sound came through. Connected test tv to connection in garage. No picture or sound came through on tv. Grabbed tester for coax cable. Connected end to garage and living roo,m port. Signal came through on cord itself running from booster to hook ups in garage and living room. Connected long cable to living room tv to bedroom were signal came through and ran channel tuning on tv. Tv picked up 27 channels. Picture and sound came through on tv when running cord from tv to bed room. Signal only coming in booster location and bedroom. Connected test tv to outside connection in compartment. Picture and sound came through. Switch connections from good tv signal line to bad line and picture came through. Boosyer is bad. Parts request submitted fornnew booster
79109	5	LIGHT FALLING OFF IN KITCHEN PANTY DOOR	Pantry light During pdi noticed the led light strip in the pantry had fallen off. Pictures taken. Grabbed tape prime and applied to wall were strip would stick to. Placed led strip in place and let sit and stick to wall. Pictures taken. Light stays in place
79109	10	BED ROOM DOOR TRIM TORN	Damanged bathroom trim During pdi notcied the bathroom door trim had been damaged. Mixed wood putty with ole english to color putty and blend better into scratch and cover.
79109	11	TRIM IN GARGE UPPER BUNK FALLING OFF	

Claim : 79109

WO #	Job #	Description	JOB INFORMATION
		Upper bunk trim	During pdi noticed the upper bunk trim had come loose around wall. Added silcione to back of trim and pushed in to help silicone sit and stick in place. Pictures taken.
79109	13	TRIM IN THE STEPS ARE COMING OUT	Rear entry door step trim During pdi noticed door step trim was coming out of track. Pushed all trim in to lock back in place. Used pick to for back in track and run all the way in.

Part No	Job#	Description	PARTS	Qty	Price	Total
10681	2	10681 Window - Framed - 8800 - 12		1.00	55.04	55.04
34541	3	Door - Cab - CHSQ - 15.50 x 46 -		1.00	37.39	37.39
35125	4	Top - Pressed - Kuna Black - 1.25		1.00	86.88	86.88
32758	8	Mirror - Safety Backed - 8.25 x 3		1.00	8.59	8.59
34536	8	DOOR - Cab - CHSQ - 13.25 x 39.25		1.00	30.58	30.58
34303	8	PULL - Cabinet Door - T-Pull _ 7.		1.00	1.55	1.55
13636	8	HINGE - 6 Way Compact - Soft Clos		2.00	1.59	3.18
34518	9	Door - DF - 9 x 26.50 - Harmony L		1.00	26.53	26.53
25397	12	Cap Lens - Center - 1110mm Matte		1.00	30.11	30.11
13414	14	Speaker - Wall Mount - Black - JB		1.00	28.52	28.52
34984	15	Cable - Power Supply - 4TV - Blac		1.00	22.57	22.57
3107612	15	SPLITTER 2-WAY SATELLITE		1.00	15.59	15.59

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.50	185.00	92.50
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.50	185.00	92.50
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.08	185.00	14.80
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.12	185.00	22.20
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.10	185.00	18.50
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.03	185.00	5.55
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.02	185.00	3.70
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.15	185.00	27.75
Z990	8	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	8	MISC LABOUR CODE (EXTERNAL)		0.05	185.00	9.25
Z990	8	MISC LABOUR CODE (EXTERNAL)		0.15	185.00	27.75
Z990	8	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	9	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	9	MISC LABOUR CODE (EXTERNAL)		0.08	185.00	14.80
Z990	9	MISC LABOUR CODE (EXTERNAL)		0.04	185.00	7.40
Z990	9	MISC LABOUR CODE (EXTERNAL)		0.08	185.00	14.80

Claim : 79109

Lab Code	Job#	Description LABOUR	Hrs	Rate	Total
Z990	12	MISC LABOUR CODE (EXTERNAL)	0.00	185.00	0.00
Z990	12	MISC LABOUR CODE (EXTERNAL)	0.00	185.00	0.00
Z990	12	MISC LABOUR CODE (EXTERNAL)	0.40	185.00	74.00
Z990	14	MISC LABOUR CODE (EXTERNAL)	0.13	185.00	24.05
Z990	14	MISC LABOUR CODE (EXTERNAL)	0.07	185.00	12.95
Z990	15	MISC LABOUR CODE (EXTERNAL)	0.00	185.00	0.00
Z990	15	MISC LABOUR CODE (EXTERNAL)	1.25	185.00	231.25
Z990	15	MISC LABOUR CODE (EXTERNAL)	0.21	185.00	38.85
Z990	15	MISC LABOUR CODE (EXTERNAL)	0.04	185.00	7.40
Z990	5	MISC LABOUR CODE (EXTERNAL)	0.10	185.00	18.50
Z990	10	MISC LABOUR CODE (EXTERNAL)	0.10	185.00	18.50
Z990	11	MISC LABOUR CODE (EXTERNAL)	0.10	185.00	18.50
Z990	13	MISC LABOUR CODE (EXTERNAL)	0.00	185.00	0.00
Z990	13	MISC LABOUR CODE (EXTERNAL)	0.10	185.00	18.50

Excode	Job#	Description EXTRAS	Qty	Price	Total
FRT	2	DROP SHIP - WINDOW	1.00	10.85	10.85
FRT	8	FRT - JOB 8	1.00	11.12	11.12
FRT	14	FREIGHT	1.00	137.76	137.76

Parts Total:	346.53
Labour Total:	814.00
Sublet Total:	0.00
Extras Total:	159.73
>>>>> Claim Total:	1,320.26

Customer Signature:_____ Date: _____