



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72145
Promised Date:
no add 26



WO #: 72145

Customer Name: 1000 - MYERS "RV"
CENTER, INC.

Completed Date: 26 AUG 26

Invoice#:

Author: BRIAN

Stock Desc: 9579 2026 DUTCH STAR
4081

Serial#: 611863

Date In: 06 AUG 25

Chassis#: 4UZFHFE8TCWR9220

Time In:

Miles/Hrs: 1519

Tag#:

Purchased Date:

Warranty Date:

Job #1 - Internal

CHECK IN NEW UNIT

Subtotal for Job #1: 0.00

Job #2 - Internal

COMPLAINT: PRE-PDI

CAUSE: Inspection

CORRECTION: Complete

Labor

Job #	Description	Total
2	PRE-PDI	N/C

Parts

Part #	Description	Qty	Price	Total
16058	SLICK SLICK STUFF - LUBE SPRAY	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: Front emblem is peeling off

CAUSE: Double sided tape used to adhere the emblem was full of dust and debris not sticking to the front cap

CORRECTION: Order a new emblem with the adhesive on it. Will have to clean the front cap and apply new emblem.

1.00HRS

Labor

Job #	Description	Total
3	FRONT EMBLEM	185.00

Parts

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------

Customer #: 1000
MYERS "RV" CENTER,
INC.,



118281 DECAL NEWMAR RIDGE LETTER 1.00 71.20 71.20
BADGE

Subtotal for Job #3: 256.20

Job #4 - Warranty

COMPLAINT: Missing Oasis reservoir cap

CAUSE: Missing the cap for the Oasis reservoir

CORRECTION: Order and install

Used a plastic bag and a rubber band for now to prevent dirt from getting in.
.20HRS

Labor

Job #	Description	Total
4	OASIS CAP	18.50

Parts

Part #	Description	Qty	Price	Total
028181B	BOTTLE OVERFLOW CAP ONLY	1.00	21.70	21.70

Subtotal for Job #4: 40.20

Job #5 - Warranty

COMPLAINT: No video detected right turn camera

CAUSE: LOOSE CONNECTION AT MONITOR

CORRECTION: RESECURED AND SECURED WIRING
.25HRS

Labor

Job #	Description	Total
5	RIGHT TURN CAMERA	46.25

Subtotal for Job #5: 46.25

Job #6 - Warranty

COMPLAINT: Battery not charging inverter INOP

CAUSE: Setting were wrong on the inverter panel

CORRECTION: Spoke with Jason at Newmar case 1024896.
1.20HRS

Went through the settings in the panel and inverter, got it working as designed per Jason.

Labor

Job #	Description	Total
6	INVERTER	222.00

Subtotal for Job #6: 222.00

Job #7 - Warranty

COMPLAINT: Entry door awning INOP

CAUSE: There was no power to the controller for the entry door awning

CORRECTION: I called and talked to several people trying to figure out this awning, including Newmar KIBE Gerrard. Case number 102-6073. While Ive been on hold with everybody doing some poking around I found that there was no power run to the controller or no ground. I had to make a small jumper wire to get ground and I was able to plug in the spade connector for Power. I also had to call Gerard to get them to. Through re-pairing process. Everything is now working as designed. Job completed.

W/O: 72145
Promised Date: 08 APR 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,



3.50HRS

Labor

Job #	Description	Total
7	ENTRY DOOR AWNING	647.50

Subtotal for Job #7: 647.50

Job #8 - Warranty

COMPLAINT: Sliding bedroom door not secured

CAUSE: The bracket that ties the two doors connected wasnt attached to both doors

CORRECTION: Loosened the bracket, attached the other door, tested function, and adjusted the tilt of the door slightly. Job completed.

.30hrs

Labor

Job #	Description	Total
8	BEDROOM DOOR	92.50

Subtotal for Job #8: 92.50

Job #9 - Warranty

COMPLAINT: Transferred to RV*72145-1 on 19 AUG 26

Estimate amount was 0.00

Door and cabinet inserts are shrinking throughout unit

CAUSE: Dry climate, wood shrinks

CORRECTION: In the corners of all the cabinets is a darker outline of the panel. Use a stain pen to color fill the bare wood

order a stain pen and use to fill in all bare areas.

Also need to order the white paint for the cabinets for touchup.

2.00hrs

Labor

Job #	Description	Total
9	CABINET INSERTS	0.00

Subtotal for Job #9: 0.00

Job #10 - Warranty

COMPLAINT: Cabinet door gaps are crooked

CAUSE: Several cabinet door gaps were not aligned properly

CORRECTION: Using the adjustments on the hinges, adjusted the door gaps. Job completed.

.20HRS

Labor

Job #	Description	Total
10	CABINET DOORS	129.50

Subtotal for Job #10: 129.50

Job #11 - Warranty

COMPLAINT: Cutting boards unglued from stove cover

CAUSE: Silicone failed to adhere the cutting board to the countertop stove cover

CORRECTION: I had to scrape the silicone from the stove covers and the cutting boards clean with adhesive cleaner apply silicone adhesive for plastics and use a battery to weigh them down for the weekend. Job completed.

.80HRS

W/O: 72145
Promised Date: 08 APR 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,



W/O: 72145
Promised Date: 08 APR 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,



Labor				
Job #	Description			Total
11	CUTTING BOARDS			148.00
Parts				
Part #	Description	Qty	Price	Total
18012	TRANSLUCENT GLAZING SILICONE 10 OZ	1.00	6.80	6.80
Subtotal for Job #11:				154.80

Job #WIN-DLX - Internal
COMPLAINT: WINTERIZE INCLUDE W/D, ICEMAKER

CAUSE: Winter is coming.

CORRECTION: Done.

Labor				
Job #	Description			Total
WIN-DLX	WINTERIZE RV - DELUXE CLASS A			N/C
Parts				
Part #	Description	Qty	Price	Total
21622	ANTIFREEZE	8.00	N/C	N/C
Subtotal for Job #WIN-DLX:				0.00

Parts Total: 99.70
Labour Total: 1,489.25
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 1,588.95

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 26 Aug 2026

