



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73379
Promised Date:
24 1111 26



WO #: 73379 (Appointment Date: 19 MAY 2026 - Time: 09:15am)

Customer Name: 61287 - HARRISON,
BERRETT L

Completed Date: 23 JUL 26

Invoice#:

Author: ADVISOR

Stock Desc: 9638 2026 LACROSSE
3510DB

Serial#: 5ZT2LC0B3TB012590

Date In: 19 MAY 26

Chassis#: 5ZT2LC0B3TB012590

Time In:

Miles/Hrs:

Tag#: 7326

Purchased Date: 19 MAR 26

Warranty Date: 19 MAR 26

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES DRAWERS IN THE FRONT BEDROOM DO NOT OPEN, CLOSE OR OPERATE CORRECTLY

CAUSE: Out of adjustment. Broken guides on one drawer

Replace drawer guide in bedroom cabinet

CORRECTION: Performed rail adjustments on 6 drawers at .2 each. 1.2 hrs total. Order and replace damaged drawer guides on one drawer. Attempted installation of new guides and did not fit correctly into brackets causing damage.

Re order guides and new support brackets..

Replaced both drawer guides and tested . Done

Labor

Job #	Description	Total
1	CABINET DRAWERS	228.00

Parts

Part #	Description	Qty	Price	Total
F100654455	DRAWER SLIDE, CABINET MEMBER ONLY 10"	2.00	2.75	5.50
F100654456	DRAWER SLIDE, DRAWER MEMBER ONLY 10"	2.00	0.91	1.82

Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	5.00	5.00

Subtotal for Job #1: 240.32

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES THE RECEPTACLES ON KITCHEN SLIDE ARE NOT WORKING

CAUSE: Bad connection at outlets

CORRECTION: Repaired, completed
1.0 hr

Customer #: 61287
HARRISON, BERRETT L



W/O: 73379
Promised Date: 24 JUL 26



Customer #: 61287
HARRISON, BERRETT L



Labor		
Job #	Description	Total
2	RECEPTACLES (2)	0.00
Subtotal for Job #2:		0.00

Job #3 - Warranty

COMPLAINT: JOB ADDED: CUSTOMER STATES SLIDING DOOR IN FRONT BEDROOM BATHROOM IS COMING OFF THE GUIDES

CAUSE: Lower guide loss of contact due to improper installation location from factory

CORRECTION: Modified guide to accommodate location. Tested. Completed

.5 hr requested

Lower door track had to be relocated and trim to fit to prevent overlapping of the door frame so it can sit flush.

Labor		
Job #	Description	Total
3	BATHROOM POCKET DOOR	38.00
Subtotal for Job #3:		38.00

Job #4 - Warranty

COMPLAINT: JOB ADDED: CUSTOMER STATES THE UPPER SUPPORT BRACKET HAVE PULLED AWAY FROM THE REFRIGERATOR

CAUSE: Support bracket damaged. Stylus damaged

CORRECTION: Order new support bracket. Order new stylus 1.5 wide 36 long. Remove refrigerator to replace bracket. Remove and replace stylus. 2.0 hrs requested.

Installed new stylus. Need refrigerator support bracket

Had to fabricate aluminum support bracket and paint. Installed. Completed. Asking for additional .5 hr due to bracket paint and fabrication.

Labor		
Job #	Description	Total
4	BRACKET, WALL - REFRIGERATOR	285.00

Parts				
Part #	Description	Qty	Price	Total
F100857402	STILE, PRAIRIE BROWN	1.00	3.45	3.45

Other Services				
Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	0.00	0.00

Subtotal for Job #4: 288.45

Job #5 - Internal

COMPLAINT: JOB ADDED: CUSTOMER STATES WHEN USING FRESH WATER, IN SINKS & SHOWERS IT'S VERY FOAMY, SMELLS & TASTES LIKE CHEMICALS. - CUST. BELIEVES WHEN UNIT WAS DE-WINTERIZED THE ANTIFREEZE WAS RAN THRU THE FILTER

CAUSE: Flush system. Flush water heater. Replace filter

CORRECTION: Completed

1.0 hr

Labor		
Job #	Description	Total
5	WATER FILTER	N/C

Parts				
Part #	Description	Qty	Price	Total



10-0373 EVO SPUN PP REPACEMENT 1.00 N/C N/C
CARTRIDGE

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: JOB ADDED: CUSTOMER STATES SPARE TIRE COVER FLEW OFF

CAUSE: Missing

CORRECTION: Order
Replaced. Completed

Labor

Job #	Description	Total
6	SPARE TIRE COVER	0.00

Parts

Part #	Description	Qty	Price	Total
20X47595A	COVER, TIRE 15" BLACK - NO LOGO	1.00	14.71	14.71

Subtotal for Job #6: 14.71

Job #NOTE - External

COMPLAINT: CUSTOMER WOULD LIKE TO KNOW IF SOMETHING CAN BE DONE TO KEEP THE AUTO DETECTOR CONVERTER CLOSED DURING TRANSIT? **AND WHEN PULLING IN SLIDE MATER BED NEEDS TO BE LIFTED AT FOOT TO CLOSE**

CAUSE: CUSTOMER HAS OPEN WO#73592

Subtotal for Job #NOTE: 0.00

Parts Total: 25.48
Labour Total: 551.00
Sublet Total: 0.00
Extras Total: 5.00

WORK ORDER TOTAL: 581.48

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 23 Jul 2026

W/O: 73379
Promised Date: 24 JUL 26



Customer #: 61287
HARRISON, BERRETT L

