GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13904

Date In:	03 AUG 26	Author:	MGRAY
Promised Date:	07 AUG 26	Stock No:	10846
:		Year:	2023
Customer Name:	1020 - GRAND DESIGN	Manufacturer:	GRAND DESIGN
Address:	11333 COUNTY RD 2	Brand:	REFLECTION 150 SERIES
:	MIDDLEBURY, IN	Model:	226RK
Postal/Zip:	46540	Miles/Hrs:	
Phone#(res):	888-825-2820	Exterior Color:	
Phone#(bus):		Unit Type:	FW-FIFTH WHEEL
Cell Phone:		License#:	
Email:	NONE	Tag#:	
Purchased Date:	20 FEB 24	:	
Delivery Date:	10 APR 24	:	
InService Date:		:	
Serial#:	573FR2829P3345739	:	

Job #	Description	JOB INFORMATION	Type	Bill To	
1	hard promise 8/7, has rt66		E	17231	SCHEI
2	COMPLAINT:	the rear ods stabilizer jack is not going all the way back up or down.	E	17231	SCHEI
	CAUSE:	Test rear stabilizers for operation. Not extending or retracting. When testing, notice that the inner legs are really loose inside the outer legs. The groove that keeps them aligned are wore out. Will need to replace both stabilizer. Pic uploaded.			
	CORRECTION:	...			
RI	COMPLAINT:	PREFORM ROOF INSPECTION AND ADVISE IF REPAIR IS NEEDED.	W	1020	GRAND
	CAUSE:	Roof inspection.			
	CORRECTION:	Found 2 soft sheets of decking in the middle of roof. From water intrusion around mushroom vents. Will need roof replacement. 30' white. 2 sheets of decking. REQ: 45 HOURS			
1009	COMPLAINT:	RETAIL CUSTOMER REPAIR 05 remove customers pin box adaptor.	E	17231	SCHEI
	CAUSE:	Remove customer pin box adaptor. Then reinstall when done.			
	CORRECTION:	Done.			

Continued on page 2

Work Order : 13904

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total
RI	677917008032	TPO 8FT6IN X 30FT DIFLEX		W-1020	0	531.95	0.00
2	8220160087	JACK ELECTRIC LH 4 POINT		E-17231	0	456.62	0.00
2	822060086	JACK ELECTRIC RH 4 POINT		E-17231	0	486.67	0.00
RI	677917009992	BUTYL TAPE GREY		W-1020	0	8.24	0.00
RI	677917000333	Dicor 501LSW-1 EPDM Self		W-1020	0	8.78	0.00

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
RI	Z991	PREFORM ROOF INSPECTIO		TD	W-1020	0.00	140.00	0.00
1009	Z990	MISC LABOUR CODE (EXTE		TD	E-17231	0.12	130.00	15.60
RI	Z991	PREFORM ROOF INSPECTIO		TD	W-1020	0.30	140.00	42.00
1009	Z990	MISC LABOUR CODE (EXTE		TD	E-17231	0.38	130.00	49.40
RI	Z991	PREFORM ROOF INSPECTIO		TD	W-1020	0.00	140.00	0.00
2	DIAG	DIAGNOSTICS		TD	E-17231	0.00	130.00	0.00
2	DIAG	DIAGNOSTICS		TD	E-17231	0.10	130.00	13.00
RI	Z991	PREFORM ROOF INSPECTIO		TD	W-1020	0.00	140.00	0.00
RI	RV31J-1	ROOF REPLACE RUBBER CO			W-1020	0.00	140.00	0.00

Job #	Excode	Description	EXTRAS	bill to	Qty	Price	Total
1	SSE	SHOP SUPPLIES - EXTERNAL		E-17231	1.00	5.85	5.85

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
E	17231	0.00	78.00	0.00	5.85	4.63	88.48
W	1020	0.00	42.00	0.00	0.00	0.00	42.00
	Totals	0.00	120.00	0.00	5.85	4.63	130.48

&k2S
&k0S