



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27631



WO #: 27631 (Appointment Date: 27 AUG 2026 - Time: 09:00am)

Customer: 93876 - RICKER, JERRY
Address: 670 BISHOP LOOP
GREENEVILLE, TN
37743

Home Phone: 864-979-3711

Work Phone:

Author: T.HAYES

Location: IH

Invoice #:

Stock #:
Stock Desc: 2024 FOREST RIVER FORESTER
Model:
Serial #: 1FDXE4FN9RDD42039
Chassis #:
Mileage: 7836
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 26 AUG 26
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date:

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES THE WINDOW BEHIND DRIVERS SEAT IS LEAKING - PLEASE CHECK AND ADVISE

CAUSE: CUST STATED THEY HAD WATER COMING IN THE WINDOWS WHEN IT RAINS. WATER SOWER TEST PREFORMED.

CORRECTION: REPLACE WINDOW
LABOR 1.0

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES THE WINDOW ABOVE THE SINK IS LEAKING - PLEASE CHECK AND ADVISE

CAUSE: CUST STATED THEY HAD WATER COMING IN THE WINDOWS WHEN IT RAINS. WATER SOWER TEST PREFORMED.

CORRECTION: REPLACE WINDOW
LABOR 1.0

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES BATHROOM MAGANET PULLED OUT AGAIN. PLEASE CHECK AND ADVISE

CAUSE: FOUND MAGNET THAT HOLDS DOOR OPEN FOR BATHROOM HAS PULLED OUT FROM DOOR. DOOR IS NOT STRONG ENOUGH TO HOLD

CORRECTION: RECOMMEND THROUGH BOLT
LABOR .30

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: CUSTOMER STATES FRONT DOOR STILL DONT COLSE PROPERLY - PLEASE CHECK AND ADVISE

CAUSE: DOOR STRIKER HITTING LATCH PLATE CAUSING DOOR TO SHUT HARD.

Customer #: 93876
RICKER, JERRY



CORRECTION: ADJUST DOOR TO CLOSE PROPERLY
LABOR .40

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: CUSTOMER STATES THE 2ND UNDERBELLY ON THE PASSANGERS SIDE DONT HAVE SCREWS IN IT - PLEASE CHECK AND ADVISE

CAUSE: COMPERTMENT PAN IS HANGING DOWN DUE TO SCREWS MISSING.

CORRECTION: RECOMMEND INSTALLING SCREWS AND RESEAL
LABOR .40

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: CUSTOMER STATES THE LANAMATE IN THE BATHROOM IS PEELING OF CABINETS - PLEASE CHECK AND ADVISE

CAUSE: VERIFIED THERE ARE 2 CABINETS IN THE BATHROOM THAT THE OVERLAY IS PEELING OFF.

CORRECTION: REMOVE AND REPLACE 2 CABINETS
LABOR TO REPLACE BOTH CABINET DOORS 1.0

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: CUSTOMER STATES THE DRIVERS SIDE REAR COMPARTMENT IS STILL LEAKING - PLEASE CHECK AND ADVISE

CAUSE: SPRAYED WITH WATER WATER AND FOUND THE SEAL IS DAMAGED ALLOWING WATER TO PASS THROUGH TO STORAGE AREA.

CORRECTION: REMOVE DAMAGED SEAL ON COMPARTMENT AREA AND REPLACE WITH NEW.
LABOR 1.0

Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: CUSTOMER STATES THE ROD IN THE BACK CLOSET FELL DOWN - PLEASE CHECK AND ADVISE

CAUSE: CLOTHES ROD IN CLOSET HAS PULLED DOWN AND THE SCREWS HAVE PULLED LOOSE.

CORRECTION: NEED TO RESECURE WITH LONGER SCREWS
LABOR .30

Subtotal for Job #8: 0.00

Job #9 - External

CUSTOMER STATES REAR CARGO BAY HAS LOOSE SCREWS - PLEASE CHECK AND ADVISE

Subtotal for Job #9: 0.00

Job #10 - External

CUSTOMER STATES THEY LOST A HUB CAP - WOULD LIKE TO HAVE REPLACED - PLEASE CHECK AND ADVISE

W/O: 27631



Customer #: 93876
RICKER, JERRY



Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

Subtotal for Job #10: 0.00

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 03 Sep 2026

Customer Signature : _____

W/O: 27631



Customer #: 93876
RICKER, JERRY

