



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

Estimate: 27674 PRESNELL, GARY



Estimate: 27674 (Appointment Date: 15 SEP 2026 - Time: 09:00am)

Customer: 92539 - PRESNELL, GARY
Address: 99 ROCKY LN
MIDWAY, TN
37809

Home Phone: 817-773-0840

Work Phone:

Author: CLP

Location: IH

Invoice #:

Stock #:
Stock Desc: 2022 A FLEETWOOD BOUNDER 36F
Model: 36F
Serial #: 1F66F5DN6M0A15414
Chassis #:
Mileage: 13500
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 08 SEP 26
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date:

Job #1 - External

CUSTOMER STATES THAT NEITHER OF THE TOILETS HOLD WATER - PLEASE CHECK AND ADVISE

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	0.00	0.00

Subtotal for Job #1: 0.00

Job #2 - External

CUSTOMER STATES THERE IS A YELLOW LINE THAT THEY WANT TO MAKE SURE IT IS HOOKED UP RIGHT, AND WILL NOT LEAK - PLEASE CHECK AND ADVISE

Subtotal for Job #2: 0.00

Job #3 - External

CUSTOMER STATES ON THE AWNING, SHE HAS A SUNSHADE THAT ZIPS, AND WOULD LIKE FOR SOMEONE TO ZIP IT BACK TOGETHER FOR HER - THE PARTS ARE LAYING IN THE FRONT PASSANGER SEAT.

Subtotal for Job #3: 0.00

Job #4 - External

CUSTOMER STATES THE BACK HALLWAY BATH IS LEAKING WATER INTO THE FLOOR NOT SURE IF ITS THE FOOT PEDAL, OR AROUND THE FLOOR - PLEASE CHECK AND ADVISE

Subtotal for Job #4: 0.00

Job #5 - External

CUST ADDED TO CHECK THE BATTERIES TO MAKE SURE THEY ARE OK AFTER THE WATER GOT ONTO THEM



Subtotal for Job #5: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
Tax Total: 0.00
Estimate Total: 0.00

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 14 Sep 2026

