GREENEWAY RV
SALES & SERVICE
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
(715) 325-5170
mail@greenewayrv.com
www.greenewayrv.com
[spreading the joy of the camping lifestyle]

W/O: 13421
Promised Date: 07 AUG 26

WO #: 13421
Customer Name: 90447 - ANDERSON, SEAN
Address: 5980 DUSTY LN
SO BELOIT, IL
Postal/Zip: 61080
Phone#(res): 815-543-2240
Phone#(bus):
Cell Phone:
Email: CRAZYFAM4@ICLOUD.COM

Date In: 27 APR 26
Promised Date: 07 AUG 26

Purchased Date: 21 SEP 24
Delivery Date: 26 SEP 24
InService Date:
Serial#: 4X4TPUP29RP102001

Author: DLUCAS
Stock No: 11140
Year: 2024
Manufacturer: FOREST RIVER
Brand: PUMA DESTINATION
Model: 38RLB
Miles/Hrs: 0
Exterior Color:
Unit Type: TT-TRAVEL TRAILER
License#:
Tag#: 5/27- NCP COMING

Customer #: 90447
ANDERSON, SEAN

Job #SC - External
CUSTOMER REQUESTS SERVICE CALL TO 380 WOODBRIDGE WAY ROME

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES - EXTERNAL	1.00	N/C	N/C
SC	SERVICE CALL	15.00	N/C	N/C
SC	SERVICE CALL	15.00	N/C	N/C

Subtotal for Job #SC: 0.00

Job #1 - Warranty
COMPLAINT: CUSTOMER STATES AC UNIT INOP COMPRESSOR WILL NOT COME ON BUT FAN COMES ON

CAUSE: for one it's to cold outside to test ac's but I used heat gun to fake thermostat on rear ac the fan and compressor does come on I did a amp draw that was 6.8 on compressor wire ac voltage 120 and 12 volts 13.65 I also checked the microfarards in capacitor is 65,ooo is good checked ac on a warmer day it's 74 degrees outside temperature coming out of ac is 74 degrees amp draw of compressor 6.8amps delta temp of 0 the ac is low coolant needs new ac

CORRECTION: removel of old ac unit and control module to ac I had to wire in the new control board and re attached the new ac after install I also tested ac and all new functions on new t stat as well everything is working still need new return air grill AIR RETURN GRILL COMPLETE ALL IS GOOD.

Labor

Job #	Description	Total
1	MULTIPLE LABOR CODES	603.75

Other Services

Code	Description	Qty	Price	Total
M	MISCELLANEOUS NCP FROM GE RGRED1A	1.00	0.00	0.00

Subtotal for Job #1: 603.75

Job #2 - Internal
SERVICE CALL 380 WOODBRIDGE WAY

© 2026 Integrated Dealer Systems

Other Services

Code	Description	Qty	Price	Total
SC	SERVICE CALL	0.00	N/C	N/C

Subtotal for Job #2: **0.00**

Parts Total:	0.00
Labour Total:	603.75
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	**603.75**

CUSTOMERS CLEAR RECEIPT

I acknowledge receipt of the above-described vehicle and understand that the authorized service has been completed.

I understand that service and repair work addresses the concerns identified at the time of service and does not guarantee the prevention of future failures or unrelated issues.

I acknowledge that no blanket warranty is provided on service or repair work unless expressly stated in writing.

Any goodwill repairs, adjustments, or considerations are not an admission of defect, fault, or warranty obligation and do not create any ongoing responsibility.

Customer Signature : _____ Date: 14 Sep 2026

CUSTOMER WORK ORDER

W/O: 13421
Promised Date: 07 AUG 26

Customer #: 90447
ANDERSON, SEAN

© 2026 Integrated Dealer Systems