



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27717



WO #: 27717

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11368

Stock Desc: 2027 FW FOREST RIVER

SANDPIPER 3710HBFB

Model: 3710HBFB

Serial #: 4X4FSAN29VJ049441

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 17 SEP 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

Job #1 - Warranty

COMPLAINT: A SCREW UNDER THE KITCHEN SLIDE CAUSED DAMAGE TO THE LINO FLOORING.

CAUSE: NOTED ON DAF

SCREW LEFT IN FLOOR AT SLIDE OUT FROM FACTORY.

CORRECTION: REMOVE THE DAMAGE LINO BY CUTTING THE PATTERN OUT, CLEAN AREA AND
PREP FOR NEW LINO TO BE LAID AND GLUED IN PLACE.

LABOR 4.0

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: SMALL HOLE IN MIRROR CABINET DOOR FRONT BATHROOM.

CAUSE: NOTED ON DAF

NOT FILLED AND COLORED

CORRECTION: FILL, SMOOTH AND COLOR BLEND AREA

LABOR .10

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: DOMETIC TOILET LID DAMAGED. SEAT HAS A DENT ON THE RING AND SCRATCHED.

CAUSE: NOTED ON DAF

DAMAGED AT BUILD.

CORRECTION: REPLACE TOILET SEAT AND LID

LABOR .50

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: CLOSET IN FRONT BUNKROOM HAS NAILS STICKING OUT OF THE STILE AND HOLES
IN THE STILE AS WELL.

CAUSE: NOTED ON DAF

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



CORRECTION: REMOVE OR SECURE IN PLACE ALL NAILS STICKING OUT ON STRUCTURE.
REMOVE AND REPLACE THE TOP STILE PIECES WHERE THEY COME TOGETHER ON THE
CORNER. FILL, SMOOTH AND COLOR BLEND AREA'S
LABOR 1.0

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: BUNK ROOM SLIDE FASCIA HAS LOTS OF HOLES, PLACES PEELED UP, NAILS
STICKING OUT AND NOT SECURED IN PLACE CORRECTLY. THIS IS ON BOTH SIDES AND TOP.

CAUSE: NOTED ON DAF
DAMAGED FASCIA AT BUILD

CORRECTION: REMOVE BOTH SIDES, TOP AND SQUARE CORNERS ON SLIDE FASCIA AND
REPLACE WITH ALL NEW FASCIA AND SQUARES.
LABOR 1.5

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: DEEP CUT ON BUNK ROOM WALL ABOVE THE LATCH

CAUSE: NOTED ON DAF
DAMAGED AT FACTORY

CORRECTION: FILL, SMOOTH AND PLACE A LINE OF SEAM TAPE ON WALL
LABOR .30

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: COMPARTMENT DOOR RING HAS PAINT SCUFFS, PAINT MISSING AND SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: REPLACE COMPARTMENT DOOR AND RESEAL AREA
LABOR 1.0

Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: LONG COMPARTMENT DOOR ON UNIT HAS A TAG/PAPER STUCK IN THE SEALANT

CAUSE: NOTED ON DAF

CORRECTION: REMOVE THE CURRENT SEALANT, CLEAN AREA AND RESEAL
LABOR .50

Subtotal for Job #8: 0.00

Job #10 - Warranty

COMPLAINT: KITCHEN CABINET PAINT IS CHIPPED

CAUSE: NOTED ON DAF

CORRECTION: FILL AND COLOR BLEND AREA
LABOR .20



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Subtotal for Job #10: 0.00

Job #11 - Warranty

COMPLAINT: KITCHEN BACKSPLASH IS CUT

CAUSE: NOTED ON DAF

CORRECTION: REMOVE CUT BACKSPLASH, CLEAN AREA, APPLY DOUBLE SIDED TAPE TO THE NEW BACKSPLASH AND INSTALL.

REPLACE BACKSPLASH

LABOR 1.5

Subtotal for Job #11: 0.00

Job #12 - Warranty

COMPLAINT: PULL OUT DRAWER UNDER THE KITCHEN SINK IS LOOSE ON THE RIGHT SIDE WHEN OPENING IT

CAUSE: NOTED ON DAF

CORRECTION: ADJUST THE HINGE ON THE RIGHT SIDE OF THE DRAWER

LABOR .20

Subtotal for Job #12: 0.00

Job #13 - Warranty

COMPLAINT: WHITE SPOTS ON THE COUCH BACK AND SIDE

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AREAS AND IF THIS REPAIR DOES NOT WORK FILE ANOTHER CLAIM TO REPLACE

LABOR 1.0

Subtotal for Job #13: 0.00

Job #14 - Warranty

COMPLAINT: DENT IN FLOATING SHELF ABOVE TV IN LIVING AREA

CAUSE: NOTED ON DAF

CORRECTION: REMOVE AND REPLACE FLOATING SHELF

LABOR .50

Subtotal for Job #14: 0.00

Job #16 - Warranty

COMPLAINT: BOTTOM OF MASTER BEDROOM DOOR HAS A CHIP IN THE OVERLAY/DOOR

CAUSE: NOTED ON DAF

CORRECTION: REPLACE DOOR

LABOR .50

Subtotal for Job #16: 0.00

Job #17 - Warranty

COMPLAINT: VALANCE OVER BED IS STAINED AND CAUSED DAMAGE TO THE COLOR OF IT

CAUSE: NOTED ON DAF

CORRECTION: REMOVE THE ELECTRICAL OUTLETS, REMOVE THE DAMAGED VALANCE,

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

REPLACE WITH NEW VALANCE AND REINSTALL ALL ELECTRICAL OUTLETS
LABOR 1.0

Subtotal for Job #17: 0.00

Job #18 - Warranty

COMPLAINT: 3 SPOTS OF BLACK STAINS ON MASTER BEDROOM WALL

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AND COLOR BLEND AREA
LABOR .20

Subtotal for Job #18: 0.00

Job #19 - Warranty

COMPLAINT: BATHROOM CABINET STILE HAS BUBBLES ACROSS THE TOP

CAUSE: NOTED ON DAF
COLOR IS LIFTING ON CABINET

CORRECTION: SMOOTH AND COLOR BLEND AREA
NOTE TO VIN FOR FURTHER ISSUES
LABOR .20

Subtotal for Job #19: 0.00

Job #20 - Warranty

COMPLAINT: BUNK ROOM SLIDE SWITCH IS BACKWARDS

CAUSE: NOTED ON DAF
SWITCH WORKS OPPOSITE TO THE OTHER SLIDE SWITCH

CORRECTION: REMOVE SWITCH AND INSTALL CORRECTLY
LABOR .20

Subtotal for Job #20: 0.00

Job #9 - Warranty

COMPLAINT: ENTRY DOORS ARE RUSTED ON HINGES

CAUSE: NOTED ON DAF

CORRECTION: COLOR MATCH RUSTED AREA
LABOR .30

Subtotal for Job #9: 0.00

Job #21 - Warranty

COMPLAINT: AC MISSING THE INSIDE INTERIOR COVERS

CAUSE: NOTED ON DAF

CORRECTION: REPLACE INSODE AC COVER
LABOR .20

Subtotal for Job #21: 0.00

W/O: 27717



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



W/O: 27717

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 17 Sep 2026

Customer Signature : _____

Customer Work
Order



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

