

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13706

Date In:	24 JUN 26	Author:	DLUCAS
Promised Date:	03 JUL 26	Stock No:	11607
:	:	Year:	2027
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	PUMA TT
:	CHICAGO, IL	Model:	32RBFQ-2B
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB:7/10
Purchased Date:	25 MAR 26	:	:
Delivery Date:	17 JUN 26	:	:
InService Date:	:	:	:
Serial#:	4X4TPUH28VP109675	:	:

```
*****
Job #   Description                JOB INFORMATION          Type Bill To
*****
SC      CUSTOMER REQUESTS SERVICE CALL TO 1597 SOUTH SHORE   I    SAP    POLIC
        DRIVE SAINT GERMAINE
1      COMPLAINT:  CUSTOMER STATES REFER IS BLOWING FUSES,   W    1021   FORES
        ONCE AFTER 24 HOURS, CUSTOMER REPLACED
        FUSE, BLEW AGAIN LESS THAN 12 HOURS
        LATER AND AT TIMES WILL VIBRATE AND
        SHAKE VERY LOUDLY SOUNDS LIKE FAN IS
        FLUTTERING ON START UP
        CAUSE:      pics taken of refrigerator I did amp
        draw that was 7 amps I also removed the
        inside freezer cover found that the
        evaporate coil frozen up and the fan is
        caught on ice the refrigerator runs
        consistently never shuts off
        CORRECTION: Will need a new refrigerator ....
        REQUEST: 1.0
2      COMPLAINT:  CUSTOMER STATES THERE IS A GAS SMELL UP   W    1021   FORES
        FRONT NEAR TANKS EVEN WITH GAS TURNED
        OFF
        CAUSE:      pics taken I tested with my gas sniffer
        and found the 20 lb lp tank leaking
        where the valve threads into tank
        CORRECTION: Will need a new 20lb lp tank....
        REQUEST: .2
3      COMPLAINT:  CUSTOMER STATES CAN SEE LIGHT THROUGH     W    1021   FORES
        SLIDE OUT IN BOTTOM CORNER
        CAUSE:      normal suggestions customer to add steel
        wool in corners can't seal needs room to
```

Continued on page 2

Work Order : 13706

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
allow draining
CORRECTION: normal no issues REQUEST: .1
4 COMPLAINT: CUSTOMER STATES COMPARTMENT DOOR TO          W      1021    FORES
ACCESS WASHER/DRYER AREA WATER COMING IN
CAUSE:      pics taken customer found it wasn't
latched
CORRECTION: door is ok NPF
5 COMPLAINT: CUSTOMER WOULD LIKE TOILET CHECKED,          W      1021    FORES
APPEARS TO BE WOBBLY
CAUSE:      loose flange bolts to toilet
CORRECTION: tighten toilet bolts the toilet is now
secured (CUSTOMER CALLED IN AND IS
CONCERNED ABOUT SEWER SMELL IN BATHROOM
SINCE REPAIR) REQUEST: .2
6 SERVICE CALL SPLIT SVC/SALES                          I      SEP     POLIC
7 COMPLAINT: Customer states while taking shower          W      1021    FORES
water leaks onto floor
CAUSE:      the water running down shower doors and
bounces off silver glass block on bottom
of shower track and pouring over do they
make wider shower door seals does mfg
have any suggestions pics taken almost
looks like lower roller could be tighter
to pull glass inwards we need to talk
with mfg for suggestions
CORRECTION: maybe wider shower door seals

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
1 WARR  MANUFACTURER WARRANTY JS W-1021  0.00  140.00  0.00
2 WARR  MANUFACTURER WARRANTY JS W-1021  0.50  140.00  70.00
3 WARR  MANUFACTURER WARRANTY JS W-1021  0.50  140.00  70.00
4 WARR  MANUFACTURER WARRANTY JS W-1021  0.50  140.00  70.00
5 WARR  MANUFACTURER WARRANTY JS W-1021  0.50  140.00  70.00
7 WARR  MANUFACTURER WARRANTY JS W-1021  0.50  140.00  70.00
1 WARR  MANUFACTURER WARRANTY JS W-1021  0.50  140.00  70.00
1 L230  REFRIGERATOR (SINGLE D W-1021  0.00  140.00  0.00

```

```

*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
SC SSE  SHOP SUPPLIES - EXTERNAL I-SAP  1.00  0.00  0.00
SC SC   SERVICE CALL          I-SAP  0.00  3.75  0.00
6 SC   SERVICE CALL          I-SEP  0.00  3.75  0.00

```

Continued on page 3

Work Order : 13706

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	1021	0.00	420.00	0.00	0.00	0.00	420.00
	Totals	0.00	420.00	0.00	0.00	0.00	420.00

&k2S
&k0S