GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 14126

Date In:	14 SEP 26	Author:	MDFERKEY
Promised Date:	15 SEP 26	Stock No:	11365
:		Year:	2025
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	CEDAR CREEK EXPERIENCE
:	CHICAGO, IL	Model:	35RL
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	
Phone#(bus):	219-534-3167	Unit Type:	FW-FIFTH WHEEL
Cell Phone:		License#:	
Email:	NONE	Tag#:	
Purchased Date:	09 SEP 26	:	
Delivery Date:	11 SEP 26	:	
InService Date:		:	
Serial#:	4X4FCRL23SS234489	:	

Job #	Description	JOB INFORMATION	Type	Bill To	
1	COMPLAINT:	Customer states one AC thermostat reads way differently from the others.	W	1021	FORES
	CAUSE:	Found zone 3 was reading 20 or so degrees lower than the other two zones. Verified external sensors were being utilized on zones 2 and 3. Warmed temp sensor and confirmed movement at thermostat for both zones 2 and 3. Bad room temp sensor for zone 3.			
	CORRECTION:	Replaced zone 3 room temp sensor. All three zones read within a margin of error. Checks OK.			

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total
1	755790406937	ROOM SENSOR BLACK		W-1021	1	13.42	13.42

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
1	DIAG	DIAGNOSTICS		MF	W-1021	0.50	140.00	70.00
1	RV22-20	A/C REMOTE SENSOR R&R		MF	W-1021	0.50	140.00	70.00

Continued on page 2

Work Order : 14126

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	1021	13.42	140.00	0.00	0.00	0.00	153.42
	Totals	13.42	140.00	0.00	0.00	0.00	153.42

&k2S
&k0S