MYERS RV CENTER
SALES ★ PARTS ★ SERVICE

12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73781-1
Promised Date: 24 AUG 26

73781-1

WO #: 73781-1
Customer Name: 1000 - MYERS "RV" CENTER, INC.

Completed Date:
Invoice#:
Author: ADVISOR
Stock Desc: 9731 2027 OPEN RANGE COLT 17BH
Serial#: V53063
Chassis#: 58TBM0AJ5V7V53063
Miles/Hrs:
Tag#:
Purchased Date:
Warranty Date:

Date In: 25 SEP 26
Time In:

Job #01 - Warranty
COMPLAINT: Missing black tank termination handle

CAUSE: Handle was missing

CORRECTION: Order and install new black tank termination handle requesting 10 mins

Labor

Job #	Description	Total
01	MISC LABOUR CODE (WARRANTY)	N/C

Other Services

Code	Description	Qty	Price	Total
SSW	SHOP SUPPLIES - WARRANTY	1.00	N/C	N/C

Subtotal for Job #01: 0.00

Job #02 - Warranty
COMPLAINT: Wall panel by dinette is bowing very badly

CAUSE: Unknown

CORRECTION: In order to fix the Bowing wall panel by dinette I will need to remove the front side dinette seat closest to the bed ,which will require removal of backrest .to remove the backrest of the dinette seat I will need to remove the two screws securing it to the wall panel .once the screws are removed I can then start to remove the screws under the seat that secure the seat to the floor ,total of 8 screws holding seat to the floor will have to be removed . Once the 8 screws on the bottom and the two screws on top are removed I can then remove the dinette seat out of the unit so that I can then start to peel off the old seam tape so I can get access to the finish staples securing wall panel to the wall .once access is gained to the staples I need to remove all staples securing wall panel to frame .once staples are removed I need to pull the wall panel overlapping the front most panel in order to then make a line where I need to trim the wall panel so it will sit flush against the wall and not bow outwards . Once wall panel is cut to size I can then re install finish staples to secure paneling to wall .once panel is stalled to the wall I can then run a new line of seam tape over the staples to hide staples .once seam tape is installed over new staples I can then re install the 8 screws holding the dinette seat to the floor .once it is secured to the floor I can then re install the back rest for dinette seat . Requesting 3 hours for repair

Labor

Job #	Description	Total
02	MISC LABOUR CODE (WARRANTY)	N/C

Customer #: 1000
MYERS "RV" CENTER, INC.,

1000

© 2026 Integrated Dealer Systems

73781-1

Other Services

Code	Description	Qty	Price	Total
SSW	SHOP SUPPLIES - WARRANTY	1.00	N/C	N/C

Subtotal for Job #02: **0.00**

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	**0.00**

NOTICE

Due to limited storage space, a storage fee of $15 per calendar day will be charged if the unit is not picked up within 48 hours after the customer is notified that the work is complete.

Effective January 12, 2026, a 3% surcharge will be applied to all credit card transactions.

MANUFACTURER WARRANTIES AND SERVICE CONTRACTS MAY NOT COVER DIAGNOSTIC TIME WHEN NO COVERED PROBLEM OR DEFECT IS FOUND. THE CUSTOMER IS RESPONSIBLE FOR ANY DIAGNOSTIC CHARGES NOT PAID BY THE MANUFACTURER OR SERVICE CONTRACT PROVIDER.

FREEZE
DAMAGE AND WINTERIZATION

The customer is responsible for ensuring that the unit is properly winterized before leaving it with Myers RV Center, Inc. Myers RV Center, Inc. is not responsible for freeze damage to the unit or to its plumbing, water, appliance, or related systems while the unit is awaiting service, undergoing service, awaiting parts, or awaiting pickup.

If the customer wants
Myers RV Center, Inc. to winterize the unit, the customer must submit the request by text message to the Service Department and receive confirmation that the request has been received and accepted. A verbal request is not sufficient and will not be considered authorization to perform winterization. Winterization is a separate, billable service and will not be performed automatically. Myers RV Center, Inc. is not responsible for freeze damage occurring before the requested winterization service has been completed.

LOSS OR DAMAGE

Although Myers RV Center, Inc. takes reasonable precautions to protect the unit while it is in our possession, we are not responsible for loss of or damage to the unit or its contents caused by fire, theft, severe weather, or any other cause beyond our reasonable control. Customers should remove or secure valuables, including firearms, cameras, jewelry, cash, and personal belongings, before leaving the unit for service.

AUTHORIZATION

I authorize Myers RV Center, Inc. to perform the repair work described in this work order and to furnish the parts and materials reasonably necessary to complete the authorized work. I understand that Myers RV Center, Inc. is not responsible for delays caused by parts availability, supplier or manufacturer delays, shipping delays, or other circumstances beyond its reasonable control.

I authorize Myers RV Center, Inc., its employees, and its authorized vendors to operate the vehicle on streets and highways when reasonably necessary for testing, inspection, diagnosis, transportation, or delivery to a subcontracted service provider.

I acknowledge an express mechanics lien on the vehicle described in this work order to secure payment for authorized repairs, parts, materials, storage fees, and other amounts lawfully due.

Customer Signature : _____ Date: 25 Sep 2026

Customer Work Order

W/O: 73781-1
Promised Date: 31 AUG 26

73781-1

Customer #: 1000
MYERS "RV" CENTER, INC.,

1000

© 2026 Integrated Dealer Systems