

Claim Response

9/12/2022
10:49:32 am

Claim: C3202952

Item Reference no.

Non-Warranty Goodwill Adjustment
Repair start date Repair date VIN

Last Modified by: ambrl
Pre-auth Dealer Repairing dealer name

Labor rate Changed Type
warranty rate

Date of Purchase

202952	68430	8/31/2022	8/31/2022	4YDT26022M3101473	1194	Basden's American RV	150.00	0.00	SA21-414	7/22/20
					600 E Baseline Rd	Evansville, IN 47725				

18749, dealer claiming 48.79/56.11
Component Model: 6020 Component Serial Number: N 20 17

Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
696405	Regulator - Recall Only Kit - P	1.00	0.00	25.00	15.00	28.75	0.00	0.00	0.00	Approved

Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
7141442B	Safety Advisory 21-414 Winn-Tec Complaint: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414 SECTION: 71 COMPONENT: 414 OPERATION: 7141442B PART#380444 Cause: LP REGULATOR RECALL. Correction: INSTALLED NEW REGULATOR AND TESTED (Deking/KRV)		0.50	0.50	75.00	0.00	1	0.50	Approved

Submitted parts & sublet	28.75	Approved parts & sublet	28.75
Submitted labor & sublet	75.00	Approved labor & sublet	75.00
Submitted freight:	0.00	Approved freight	0.00
Tax:	0.00	Tax:	0.00
Total Submitted:	103.75	Total approved:	103.75