

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 13477B

|                 |                     |                 |                |
|-----------------|---------------------|-----------------|----------------|
| Date In:        | 12 MAY 26           | Author:         | DMCGINLEY      |
| Promised Date:  | 25 DEC 26           | Stock No:       | 10787          |
| :               | :                   | Year:           | 2023           |
| Customer Name:  | 1020 - GRAND DESIGN | Manufacturer:   | GRAND DESIGN   |
| Address:        | 11333 COUNTY RD 2   | Brand:          | REFLECTION FW  |
| :               | MIDDLEBURY, IN      | Model:          | 303RLS         |
| Postal/Zip:     | 46540               | Miles/Hrs:      | 0              |
| Phone#(res):    | 888-825-2820        | Exterior Color: | :              |
| Phone#(bus):    | :                   | Unit Type:      | FW-FIFTH WHEEL |
| Cell Phone:     | :                   | License#:       | :              |
| Email:          | NONE                | Tag#:           | :              |
| Purchased Date: | 07 MAY 26           | :               | :              |
| Delivery Date:  | 12 MAY 26           | :               | :              |
| InService Date: | :                   | :               | :              |
| Serial#:        | 573FR3425P9922405   | :               | :              |

```
*****
Job #   Description      JOB INFORMATION      Type Bill To
*****
6      COMPLAINT:  PER MATT- THE SLIDE OUT IS LEAKING AND   W    1020    GRAND
      CAUSE:        NEEDS TO BE FIXED-
      I added silicone to the rails and at the
      bottom of the tray. I sprayed the slide
      down heavily with water and no leaks are
      visible.
      CORRECTION:  Done.  REQ: 1.43 APPROVED:1.4
1      COMPLAINT:  FOUND ON THE DAY OF SHOWTHRU- THE        W    1020    GRAND
      CAUSE:        OBSERVATION CAMERA IS NOT OPERATING-
      THE BLUE POWER INDICATOR LIGHT DOES NOT
      LIGHT UP- VERIFIED POWER TO THE CAMERA
      ALL CHECKED OKAY- THER IS ALSO NO WIFI
      CONNECTION TO THE CAMERA- INTERNAL
      FAILURE OF THE CAMERA0
      CORRECTION:  R&R OBSERVATION CAMERA  REQ: .75 HOURS
      OF LABOR  APPROVED: .5  repairs being
      done at factory
2      COMPLAINT:  FOUND ON THE DAY OF SHOWTHRU- THE        W    1020    GRAND
      NAUTILUS PANEL IS CRACKED IN THE LOWER
      RIGHT CORNER
      CAUSE:        NAUTILUS PANEL IS CRACKED FROM THE LOWER
      LEFT CORNER SCREW BEING SCREWED TO TIGHT
      CORRECTION:  R&R NAUTILUS PANEL  REQ! 1 HOUR
      APPROVED:1HR
3      COMPLAINT:  FOUND ON DAY OF THE SHOWHTRU- BOTH OF    W    1020    GRAND
      THE SADDLE BOXES ARE CRACKED AROUND THE
      SCREWS AND NEEDS TO BE REPLACED
      CAUSE:        THE SADDLE BOXES ARE BOTH CRACKED AROUDN
```

Continued on page 2

Work Order : 13477B

\*\*\*\*\*  
 Job # Description JOB INFORMATION Type Bill To  
 \*\*\*\*\*  
 THE SCREWS FROM THE MANUFACTURER AND  
 NEED TO BE REPLACED  
 CORRECTION: R&R SADDLE BOXES REQ: 1.50 HOURS OF  
 LABOR APPROVED: 1.5 repairs being done  
 at factory

\*\*\*\*\*  
 Job # Part No Description PARTS Bill to Qty Price Total  
 \*\*\*\*\*  
 6 146877 NOVAFLEX SEALANT WHITE W-1020 1 9.28 9.28  
 3 822060039 SADDLE BOX 56" BLACK ABS H W-1020 0 62.34 0.00  
 1 822040153 CAMERA REAR VIEW OBSERVATI W-1020 0 833.05 0.00  
 2 8220360041 CONVENIENCE CENTER PANEL N W-1020 0 230.26 0.00

\*\*\*\*\*  
 Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total  
 \*\*\*\*\*  
 6 WARR MANUFACTURER WARRANTY JGK W-1020 0.50 140.00 70.00

\*\*\*\*\*  
 BILLINGS SUMMARY  
 Type Bill Id Parts Labour Sublet Extras Tax Total  
 \*\*\*\*\*  
 W 1020 9.28 70.00 0.00 0.00 0.00 79.28  
 Totals 9.28 70.00 0.00 0.00 0.00 79.28

&amp;k2S

&amp;k0S