



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

Estimate: 27787 SCHOLZ, ROBERT



Estimate: 27787 (Appointment Date: 06 OCT 2026 - Time: 09:00am)

Customer: 73006 - SCHOLZ, ROBERT
Address: 232 OLIVIA LEE CT
JONESBOROUGH, TN
37659

Home Phone: 941-685-0671

Work Phone:

Author: T.HAYES

Location: IH

Invoice #:

Stock #:
Stock Desc: 2023 TT GRAND DESIGN IMAGINE
2670MK
Model: 2670MK
Serial #: 573TE3223R6647509
Chassis #:
Mileage:
Key #:
Req'n #: 63126
License #:
Trim:

Purchase Date:
Date In: 05 OCT 26
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date:

Job #ROOFINS - External

COMPLAINT: COMPLEMENTARY ROOF INSPECTION

CHECK CAULKING _____

CHECK SKYLIGHTS _____

CHECK ROOF VENTS _____

CHECK LUBE & ANTENNA _____

CHECK SATELLITE _____

CHECK RUBBER _____

CAUSE: CAULKING IS CRACKING AND HAS VOIDS. RECOMEND SCRAPE AND SEAL

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	8.75	8.75

Subtotal for Job #ROOFINS: 8.75

Job #WINT2 - External

WINTERIZE-TT/CLASS C

Due to the winterization process, most refrigerator filters and water filters will need to be replaced. Because of the variability of filters, customers will be responsible for ordering/supplying the replacement filter for your unit at time of dewinterization in the spring.

Because of the number of different filters being used by manufacturers, Tri-Am RV cannot guarantee that we will have the correct filter in stock at time of the appt. Therefore, we recommend that you either pre-order your filters, or bring them with you at your appointment time.

Initial/Date: _____

Labor

Code	Description	Hours	Rate	Total
SP120140	WINTERIZE FRESH WATER SYSTEM	1	175.00	175.00

Parts

Part #	Description	Qty	Price	Total
13-1639	ANTIFREEZE -50	3	7.19	21.57

Subtotal for Job #WINT2: 196.57

Job #3 - External

COMPLAINT: CUSTOMER STATES THE BREAKER HAS BEEN TRIPPING - AT HOME HE HAS A 110 OUTLET - HE HOOKED SURG PROTECTOR WHEN CAMPING, HE SAID WHEN HE PLUGGED IT IN



NOTHING HAPPENED. PLEASE CHECK AND ADVISE

CAUSE: BREAKER IS NO GOOD.WILL NEED NEW BREAKER

Other Services

Code	Description	Qty	Price	Total
SSI	SHOP SUPPLIES INTERNAL	1	0.00	0.00

Subtotal for Job #3: 0.00

Job #4 - External

COMPLAINT: CUSTOMER STATES THAT HIS TOILET WILL NOT HOLD WATER. HE HAS A VALVE IN THE BATHROOM SINK. ***** HE DOES NOT WANT THIS ADDRESSED AT THIS TIME.

CORRECTION: CUSTOMER WILL HAVE TOILET TAKEN CARE OF AT THIS TIME, HE WILL WAIT TIL HE HAS CAMPER DEWINTERIZED.

Subtotal for Job #4: 0.00

Parts Total: 21.57
Labour Total: 175.00
Sublet Total: 0.00
Extras Total: 8.75
Tax Total: 20.02
Estimate Total: 225.34

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 06 Oct 2026

