'e-Authorization

9/16/20
11:55:24 a

e-Authorization number PA03247187 Reference no: 68463 Status: Approved Approved by flins Approved date 9/16/2022

rvicing aler	Name	Address	VIN	Retail sold on
94	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDTSGP29N3110877	7/6/2022

Ju pe of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2106802A	Slide Out Box Wir	0.00	1.00	0.50		1	0.20	Complaint:SOMETHING IS HANGING DOWN UNDER THE SLIDE. POSSIBLY THE CABLE ORGANIZER Cause:wire loom hanging down under slide out room. screw that holds the clip onto the slide frame has failed. Correction:got a larger tech screw and secured the clip and spring to it. cut old zip ties off and replaced to help hold wire loom against spring. ran slide room in and out to make sure it wasnt hanging. parked unit. KRV – Labor time approved in accordance with Keystone RV's flat rate manual.
e-Authorization number PA03247187					0.50				

r paper claims only use one pre-authorization number per warranty claim for
aple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the