



Phone: (423) 235-1167  
Toll Free: (877) 635-1167  
Fax: (423) 235-1176

1202 Idell Road  
Bulls Gap, TN 37711

WO #: 27782

Customer: 93143 - POPE, GREGORY  
Address: 1144 ELIZABETHTON HWY  
BLUFF CITY, TN  
37618  
Home Phone: 423-534-0403  
Work Phone:  
Author:SPD  
Location: IH  
Invoice #:

Stock #: 11017  
Stock Desc: 2025 C FOREST RIVER FORESTER  
3251DSLEF  
Model: 3251DSLEF  
Serial #: 1FDXE4FN0SDD26625  
Chassis #: 1FDXE4FN0SDD26625  
Mileage:12125  
Key #: 5299  
Req'n #:  
License #:  
Trim:

Purchase Date: 12 AUG 25  
Date In: 02 OCT 26  
Promise Date:  
Promise Time:  
Schedule Date:  
Completed:  
Warr. Date: 12 AUG 25

#### Job #1 - Warranty

COMPLAINT: WHEN CUST CAME TO PICK UP UNIT THYE NOTICED MORE CABINETS HAVE OVERLAY PEELING.CABINET DOOR IN BEDROOM IS PEELING AGAIN. THIS HAS BEEN REPLACED PRIOR.

CAUSE: THE ADHESIVE IS NOT HOLDING ON THE CABINET DOOR IN THE BEDROOM.

CORRECTION: REPLACE CABINET DOOR  
LABOR .50

Subtotal for Job #1: 0.00

#### Job #2 - Warranty

COMPLAINT: STILE PIECE IN THE BEDROOM ON THE RIGHT SIDE WORDROBE HAS THE OVERLAY PEELING OFF.

CAUSE: OVERLAY PEELING OFF THE STILE PIECE AT WORDROBE AREA. ADHESIVE FAILED.

CORRECTION: REPLACE THE STILE THAT IS PEELING IN THE AREA.  
LABOR .50

Subtotal for Job #2: 0.00

#### Job #3 - Warranty

COMPLAINT: THE STILE BETWEEN THE WORDROBE AND THE DRAWER ON THE RIGHT SIDE OF THE BOTTOM OF THE BED IS PEELING OFF.

CAUSE: ADHESIVE HAS FAILED ON THE STILE BOARD AND ALLOWING THE OVERLAY TO COME OFF.

CORRECTION: REPLACE THE STILE BOARD IN THE AREA  
LABOR .50

Subtotal for Job #3: 0.00

#### Job #4 - Warranty

COMPLAINT: THE OVERLAY ON THE LEFT SIDE TOP OF THE WORDROBE IN BEDROOM IS PEELING OFF.

CAUSE: ADHESIVE FAILED AND OVERLAY IS COMING OFF.

W/O: 27782

Customer #: 93143  
POPE, GREGORY

CORRECTION: REPLACE THE STILE BOARD  
LABOR .50

**Subtotal for Job #4: 0.00**

**Job #5 - Warranty**

COMPLAINT: THE STILE OVER THE BED IN THE TOP LEFT CORNER IS BUBBLED OUT AND THE  
OVERLAY IS COMING OFF THE STILE BOARD.

CAUSE: ADHESIVE HAS FAILED ON THE STILE BOARD AND COMING OFF

CORRECTION: REPLACE THE STILE BOARD IN THE AREA  
LABOR 1.0 DUE TO THE AREA AND LOCATION

**Subtotal for Job #5: 0.00**

**Job #6 - Warranty**

COMPLAINT: BATHROOM LOWER CABINET DOOR UNDER SINK OVERLAY IS COMING OFF

CAUSE: ADHESIVE ON THE OVERLAY ON CABONET IS FAILED AND ALLOWING THE OVERLAY TO  
COME OFF.

CORRECTION: REPLACE THE CABINET DOOR  
LABOR .50

**Subtotal for Job #6: 0.00**

**Job #7 - Warranty**

COMPLAINT: THE CLOSET IN BATHROOM CABINET STILE IS PEELING OFF THE STILE BOARD

CAUSE: ADHESIVE ON THE STILE BOARD HAS FAILED AND ALLOWING THE OVERLAY TO COME  
OFF

CORRECTION: REPLACE THE STILE BOARD  
LABOR .50

**Subtotal for Job #7: 0.00**

**Job #8 - Warranty**

COMPLAINT: BATHROOM MIRROR OVERLAY IS COMING OFF THE STILE

CAUSE: ADHESIVE ON THE STILE IS COMING OFF AND ALLOWING THE OVERLAY TO PEEL OFF

CORRECTION: REPLACE THE BATHROOM MIRROR  
LABOR .50

**Subtotal for Job #8: 0.00**

Parts Total: 0.00  
Labour Total: 0.00  
Sublet Total: 0.00  
Extras Total: 0.00  
**WORK ORDER TOTAL: 0.00**

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

W/O: 27782



Customer #: 93143  
POPE, GREGORY



Customer Signature : \_\_\_\_\_

Date: 02 Oct 2026

W/O: 27782



Customer #: 93143  
POPE, GREGORY



Customer Work  
Order

