



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73831
Promised Date:
26 AUG 26



WO #: 73831 (Appointment Date: 07 AUG 2026 - Time: 12:45pm)

Customer Name: 59965 - TENNYSON,
EVENLYN

Completed Date:

Invoice#:

Author: BRIAN

Stock Desc: 2025 DUTCH STAR 4325

Serial#: 611615

Chassis#: 4UZFCHFE7SCWA3863

Miles/Hrs: 9539

Tag#: 7367

Purchased Date:

Warranty Date:

Date In: 07 AUG 26

Time In:

Job #1 - External

NEWMAR case #1109196

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00
Subtotal for Job #1:				0.00

Job #2 - Warranty

COMPLAINT: GENERATOR WILL NOT SLIDE OUT

CAUSE: Cable conduit slipping in retaining bracket. Dirty latch and dry mechanism.

CORRECTION: Resecured and fastened cable conduit to frame. Cleaned and lubricated latch and mechanism. Tested. Completed. Note: Genset drawer is heavy. Give slight push to hood when pulling latch for genset to release smoothly.

1.00HRS

Labor

Job #	Description	Total
2	GENERATOR TRAY	N/C
Subtotal for Job #2:		0.00

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES THE TPMS RANDOMLY SHOWS INCORRECTLY READINGS
AFTER TRAVELING 100MILES

CAUSE: SUBLET

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: CUSTOMER STATES THE ENGINE LIGHT IS ON. SEND TO FREIGHTLINER OIL
CHANGE IN ENGINE AND GENERATOR.

CAUSE: SUBLET

Customer #: 59965
TENNYSON, EVENLYN





Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: CUSTOMER STATES THE ENTRY DOOR HANDLE LOOSE

CAUSE: Loose

CORRECTION: Tightened and tested. Handle will have some movement due to free floating grab handle design. Completed
 .30HRS

Labor

Job #	Description	Total
5	ENTRY DOOR HANDLE	N/C

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: CUSTOMER STATES THERE IS A NOISE WHILE IN TRANSIT AT PASSENGER AREA

CAUSE: Couldnt duplicate any abnormal noises on test drive.

CORRECTION: Couldnt duplicate

Labor

Job #	Description	Total
6	NOISE	N/C

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: CUSTOMER STATES BEDROOM SLIDING SEPARATING FROM OTHER DOOR

CAUSE: Out of track. Derailment

CORRECTION: Removed guide. Reinstalled into track. Adjusted and reinstalled guide. Tested. Note: be gentle. Doors are heavy and hardware is small. Completed
 .50HRS

Labor

Job #	Description	Total
7	DOORS	N/C

Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: CUSTOMER STATES AIR SYSTEM LEAKING
 (FREIGHTLINER)

CAUSE: SUBLET

Subtotal for Job #8: 0.00

Job #9 - Warranty

COMPLAINT: CUSTOMER STATES LEVELING JACKS ARE SLOW TO RETRACT

CAUSE: Dirty and dry shafts/ seals

CORRECTION: Cleaned and lubricated all jack legs and seals. Tested on retract after cleaning. Leveling system retracts normally. Completed



W/O: 73831
Promised Date: 30 SEP 26



Customer #: 59965
TENNYSON, EVENLYN



Labor		
Job #	Description	Total
9	LEVELING SYSTEM DIAGNOSE	N/C
Subtotal for Job #9:		0.00

Job #10 - Warranty

COMPLAINT: CUSTOMER STATES FRONT HOOD RUBS AT BOTTOM OF DRIVER SIDE

CAUSE: Touching

CORRECTION: Performed adjustments to bumper. Test drove and verified rubbing has been eliminated.
Completed
.50HRS

Labor		
Job #	Description	Total
10	HOOD ADJUST CLASS A	N/C
Subtotal for Job #10:		0.00

Job #11 - Warranty

COMPLAINT: CUSTOMER STATES CHECK ALL 3 AC'S FOR PROPER OPERATION AND COOLING.
WITH 3 AC'S ON COACH BARELY COOLS / REAR AC MAKING NOISE

CAUSE: Front ac delta temp at 5 degrees. Compressor amperage at 3 amps. Loss of refrigerant. Middle ac has low air flow. Rear ac ok.

CORRECTION: Replace front ac roof unit. Reseal air manifold on mid ac. Recommend coil clean service on mid and rear ac.
6.00HRS

Labor		
Job #	Description	Total
11	A/C DIAGNOSTIC TIME	N/C
Subtotal for Job #11:		0.00

Job #12 - External

CUSTOMER STATES ESTIMATE TO REPAIR DAMAGE AT DRIVER REAR

Subtotal for Job #12: 0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.



Customer Signature : _____

Date: 12 Aug 2026

W/O: 73831
Promised Date: 30 SEP 26



Customer #: 59965
TENNYSO, EVENLYN



Customer Work
Order

