MYERS RV CENTER
SALES ★ PARTS ★ SERVICE
12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 74168
Promised Date:

WO #: 74168 (Appointment Date: 06 OCT 2026 - Time: 01:45pm)
Customer Name: 62030 - HEIN, RACHEL

Completed Date:
Invoice#:
Author: BRIAN
Stock Desc: 9582 2026 LONGITUDE 285BH
Serial#: 5ZT2LNUB2T9012223
Chassis#: 5ZT2LNUB2T9012223
Miles/Hrs:
Tag#: 7519
Purchased Date: 15 AUG 26
Warranty Date: 15 AUG 26

Date In: 06 OCT 26
Time In:

Customer #: 62030
HEIN, RACHEL

Job #1 - Warranty
COMPLAINT: CUSTOMER STATES BLIND OVER KITCHEN SINK INOP

CAUSE: String broken on the far left side of the blind, which controls the louvers from moving up and down, causing improper operation of the blind

CORRECTION: Recommendation for replacement of the mini blind photos attached photo with label attached request requesting
.40HRS

Labor

Job #	Description	Total
1	Mini-Blind	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty
COMPLAINT: CUSTOMER STATES REAR DOOR WILL NOT CLOSE PROPERLY (MUST BE SLAMMED)

CAUSE: Striker plate out of adjustment
Screws not holding the striker plate in place and was moving, not allowing the door to close and lock

CORRECTION: Readjusted the striker plate added a longer screw so that it would grip and hold the striker plate in place tested the door closes easily and properly locks properly job is complete
.25HRS

Labor

Job #	Description	Total
2	ENTRY DOOR	N/C

Other Services

Code	Description	Qty	Price	Total
SSW	SHOP SUPPLIES - WARRANTY	1.00	N/C	N/C

Subtotal for Job #2: 0.00

© 2026 Integrated Dealer Systems

Job #3 - External
CUSTOMER BOUGHT PARTS

Parts

Part #	Description	Qty	Price	Total
18402	NEUTRAL GROUND BONDING PLUG	1.00	13.63	13.63

Subtotal for Job #3: 13.63

Job #WBP-F - External
COMPLAINT: WHEEL BEARING PACK - FALL SPECIAL
***Lug nuts torqued to _____
***Customer acknowledges they were advised to check torque 50-100 miles after pickup
_____

CAUSE: Customer request

CORRECTION: Completely repacked both sides tandem axle for a bearing pack, removing a tires grease caps packing nuts, cleaned repack bearings, clean spindles reinstalled the tires. The job is complete.
Estimated Amount: 385.00

Labor

Job #	Description	Total
WBP-F	BEARINGS, PACK (TANDEM AXLE)	304.83

Parts

Part #	Description	Qty	Price	Total
565-1341	BRAKE CLEANER	4.00	13.17	52.68
9916	MAGNET CLIP 10" & 12"	1.00	1.00	1.00
32532	5604 PKG/2 SEALS	2.00	8.25	16.50

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	9.99	9.99

Subtotal for Job #WBP-F: 385.00

Customer Work Order

Parts Total:	83.81
Labour Total:	304.83
Sublet Total:	0.00
Extras Total:	9.99
Tax Total:	30.40
WORK ORDER TOTAL:	**429.03**

© 2026 Integrated Dealer Systems

NOTICE

Due to limited storage space, a storage fee of $15 per calendar day will be charged if the unit is not picked up within 48 hours after the customer is notified that the work is complete.

Effective January 12, 2026, a 3% surcharge will be applied to all credit card transactions.

MANUFACTURER WARRANTIES AND SERVICE CONTRACTS MAY NOT COVER DIAGNOSTIC TIME WHEN NO COVERED PROBLEM OR DEFECT IS FOUND. THE CUSTOMER IS RESPONSIBLE FOR ANY DIAGNOSTIC CHARGES NOT PAID BY THE MANUFACTURER OR SERVICE CONTRACT PROVIDER.

FREEZE
DAMAGE AND WINTERIZATION

The customer is responsible for ensuring that the unit is properly winterized before leaving it with Myers RV Center, Inc. Myers RV Center, Inc. is not responsible for freeze damage to the unit or to its plumbing, water, appliance, or related systems while the unit is awaiting service, undergoing service, awaiting parts, or awaiting pickup.

If the customer wants
Myers RV Center, Inc. to winterize the unit, the customer must submit the request by text message to the Service Department and receive confirmation that the request has been received and accepted. A verbal request is not sufficient and will not be considered authorization to perform winterization. Winterization is a separate, billable service and will not be performed automatically. Myers RV Center, Inc. is not responsible for freeze damage occurring before the requested winterization service has been completed.

LOSS OR DAMAGE

Although Myers RV Center, Inc. takes reasonable precautions to protect the unit while it is in our possession, we are not responsible for loss of or damage to the unit or its contents caused by fire, theft, severe weather, or any other cause beyond our reasonable control. Customers should remove or secure valuables, including firearms, cameras, jewelry, cash, and personal belongings, before leaving the unit for service.

AUTHORIZATION

I authorize Myers RV Center, Inc. to perform the repair work described in this work order and to furnish the parts and materials reasonably necessary to complete the authorized work. I understand that Myers RV Center, Inc. is not responsible for delays caused by parts availability, supplier or manufacturer delays, shipping delays, or other circumstances beyond its reasonable control.

I authorize Myers RV Center, Inc., its employees, and its authorized vendors to operate the vehicle on streets and highways when reasonably necessary for testing, inspection, diagnosis, transportation, or delivery to a subcontracted service provider.

I acknowledge an express mechanics lien on the vehicle described in this work order to secure payment for authorized repairs, parts, materials, storage fees, and other amounts lawfully due.

Customer Signature : _____ Date: 09 Oct 2026

Customer Work Order

W/O: 74168
Promised Date: 09 OCT 26

Customer #: 62030
HEIN, RACHEL

© 2026 Integrated Dealer Systems