



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27770



WO #: 27770

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 11387

Stock Desc: 2027 TT KEYSTONE BULLET 26BHC

Model: 26BHC

Serial #: 4YDTBLM27VD430366

Chassis #:

Mileage:0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 29 SEP 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

Job #1 - Warranty

COMPLAINT: SLIDE WILL NOT GO IN. UPON UNIT ARRIVING THE SLIDE HAD ISSUES GOING OUT. WHEN WE TRIED TO CLOSE IT THE SLIDE WOULD GO IN ABOUT AN INCH AND STOP.

CAUSE: AFTER INSPECTION TECH DETERMINED THE SLIDE OUT CONTROL BOARD RELAYS ARE FAILING. THIS WAS NOTED ON THE DAF AS WELL.

CORRECTION: REPLACE THE SLIDE OUT CONTROL BOARD
LABOR WITH DIAG 1.5

Subtotal for Job #1: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Customer Signature : _____

Date: 06 Oct 2026

