

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 14223

Date In:	25 SEP 26	Author:	DLUCAS
Promised Date:	09 OCT 26	Stock No:	11338A
:	:	Year:	2024
Customer Name:	18039 - MCDERMOTT, CYN	Manufacturer:	CROSSROADS
Address:	N6786 COUNTRY ROAD B	Brand:	HAMPTON
:	MONTELLO, WI	Model:	375DBL
Postal/Zip:	53949	Miles/Hrs:	0
Phone#(res):	6083548065	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	cindy tam@gmail.com	Tag#:	:
Purchased Date:	17 APR 26	:	:
Delivery Date:	20 MAY 26	:	:
InService Date:	:	:	:
Serial#:	4YDTHPT29R9330480	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
SC	CUSTOMER REQUESTS SERVICE CALL TO WILDERNESS		E	18039 MC DER
	CAMPGROUND SITE C41 MONTELLO			
1	COMPLAINT: CUSTOMER STATES LEAK COMING THROUGH WINDOW AND IS BUBBLING PANEL DS SLIDEOUT IS BY SLIDING GLASS DOOR WINDOW THAT FACES ROAD		W	1021 FORES
	CAUSE: pics and measurements taken this is what I found the on door side slide the main leak is coming from the slide roof where enterabond tape did not stick and allowing water to enter down the wall and escaping through the window frame the exterior edge of slide roof is swollen and the slide floor is swollen on that same side will need a wall panel and floor and roof replacement on that side			
	CORRECTION: Will need a roof repair wall panel and floor replacement the carpet can be cleaned I will patch the area where water is getting in with enterabond tape			
2	COMPLAINT: CUSTOMER STATES MOTORIZED SHADE FRONT BEDROOM BUNCHED UP AND IS NOT WORKING		W	1021 FORES
	CAUSE: pics and measurements taken			
	CORRECTION: Will need a new shade due to rods had fallen off			
3	COMPLAINT: CUSTOMER REQUESTS ESTIMATE FOR SLIDE		E	18039 MC DER

Continued on page 2

Work Order : 14223

 Job # Description JOB INFORMATION Type Bill To

 TOPPER ODS
 CAUSE: pics and measurements taken I took pics
 of on door side slide is the biggest
 slide and the other two on off door side

CORRECTION: estimate only

 Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

 1 WARR MANUFACTURER WARRANTY JS W-1021 0.50 140.00 70.00
 2 WARR MANUFACTURER WARRANTY JS W-1021 0.50 140.00 70.00
 3 DIAG DIAGNOSTICS JS E-18039 1.00 130.00 130.00

 Job # Excode Description EXTRAS bill to Qty Price Total

 SC SSE SHOP SUPPLIES - EXTERNAL E-18039 1.00 9.75 9.75
 SC SC SERVICE CALL E-18039 0.00 3.75 0.00

 BILLINGS SUMMARY
 Type Bill Id Parts Labour Sublet Extras Tax Total

 E 18039 0.00 130.00 0.00 9.75 7.69 147.44
 W 1021 0.00 140.00 0.00 0.00 0.00 140.00
 Totals 0.00 270.00 0.00 9.75 7.69 287.44

&k2S
 &k0S