

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 14246

Date In:	28 SEP 26	Author:	DMCGINLEY
Promised Date:	15 OCT 26	Stock No:	11306A
:	:	Year:	2019
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	SALEM
:	CHICAGO, IL	Model:	261BXXL
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	RV87046
Email:	NONE	Tag#:	PLEASE TAKE PHOTOS OF
Purchased Date:	14 SEP 26	:	:
Delivery Date:	17 SEP 26	:	:
InService Date:	:	:	:
Serial#:	4X4TSMB25K7418393	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
1      COMPLAINT:  OUTDOOR UNDERLIGHTING NOT WORKING           W    1021    FORES
      CAUSE:       Check operation of out door under
                  lighting. Not working.
      CORRECTION:  Found that the wiring under the floor
                  had come disconnected. Reconnect and
                  tested good. REQ .5
2      COMPLAINT:  TIRE BLOWOUT WRAPPED AROUND CHORDS FOR       W    1021    FORES
                  HYDRAULIC LEVELING SYSTEM, WOULD LIKE US
                  TO MAKE SUER EVERYHTING IS OKAY AND/OR
                  PUT CHORD BACK WHERE IT GOES BECAUSE IT
                  IS HANGING LOW
      CAUSE:       Tire blowout damage to under belly
                  material.
      CORRECTION:  Taped up damaged area. REQ 1.5
3      COMPLAINT:  CUSTOMER STATES THEY CAN HEAR A CONSTANT E   18215    DOMRZ
                  CLICKING WHEN RUNNING THE HEAT, BELIEVED
                  TO BE COMING FROM THE FURNACE
      CAUSE:       Test furnace for operation. Customer
                  says that it makes a clicking sound when
                  running.
      CORRECTION:  I ran it for a couple of hours. Couldn't
                  duplicate any clicking noise.
4      2 BLOWOUTS, 2 FLATS, 2 SERVICE CALLS COLE HAS MORE       E    18215    DOMRZ
      INFO
WS     WINTERIZE WATER SYSTEM & TRAPS -SELF CONTAINED -       E    18215    DOMRZ
      TOWABLE
```

Continued on page 2

Work Order : 14246

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WS      009114950003 -50 F GLYCERIN FREE BASE E-18215      3      6.84      20.52
2      711217019111 4" X 180' BOTTOM BOARD - W-1021      10      0.36      3.60
4      844402074722 Advanta ST RADIAL 205/75 E-18215      3      85.09      255.27

```

```

*****
Job#  Lab Code  Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
1  DIAG      DIAGNOSTICS      TD      W-1021      0.19      140.00      26.60
3  DIAG      DIAGNOSTICS      TD      E-18215      0.50      130.00      65.00
2  DIAG      DIAGNOSTICS      TD      W-1021      0.00      140.00      0.00
WS W495      WINTERIZE RV (WATER SY JGK E-18215      0.70      130.00      91.00
1  DIAG      DIAGNOSTICS      TD      W-1021      0.31      140.00      43.40
2  DIAG      DIAGNOSTICS      TD      W-1021      1.00      140.00      140.00
4  R940      WHEEL (EACH), R & R      JT      E-18215      0.90      130.00      117.00

```

```

*****
Job #  Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
1  SSE      SHOP SUPPLIES - EXTERNAL      W-1021      1.00      20.48      20.48
WS  J-ADJ      QUOTE ADJUSTMENT      E-18215      1.00      -12.52      -12.52

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
E      18215      275.79      273.00      0.00      -12.52      29.52      565.79
W      1021      3.60      210.00      0.00      20.48      0.00      234.08

Totals      279.39      483.00      0.00      7.96      29.52      799.87

```

&k2S

&k0S