



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27877



WO #: 27877

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:
Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11149

Stock Desc: 2026 TT DUTCHMEN ASPEN TRAIL
LE 23BH

Model: 23BH

Serial #: 4YDTATL21T8920022

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 22 OCT 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

Job #1 - Warranty

COMPLAINT: WHEN DOING A LOT CHECK TECH FOUND THE BACK SPLASH OVERLAY IS COMING LOOSE FROM THE PANEL. IT IS FLAKING OFF IN A SPOT, THE OVERLAY IS VERY BRITTLE.

CAUSE: OVERLAY ON BACKSPLASH HAS CAME LOOSE IN SPOTS AND FLAKING OFF. ADHESIVE IS NOT HOLDING THE OVERLAY TO THE PANEL.

CORRECTION: REMOVE AND REPLACE THE BACKSPLASH BEHIND THE STOVE.
LABOR .50

Subtotal for Job #1: 0.00

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Customer Signature : _____

Date: 22 Oct 2026

