



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

Estimate: 27859 HILTON, DAISY



Estimate: 27859 (Appointment Date: 20 OCT 2026 - Time: 10:00am)

Customer: 92893 - HILTON, DAISY
Address: 120 ROBERT LOVE RD
ERWIN, TN
37650

Home Phone: (423) 735-9597

Work Phone:

Author: CLP

Location: IH

Invoice #:

Stock #: 10988

Stock Desc: 2025 TT FOREST RIVER

ROCKWOOD MINI 2511S

Model: 2511S

Serial #: 4X4TRLA22SD461307

Chassis #:

Mileage:

Key #: 4500

Req'n #: 63195

License #:

Trim:

Purchase Date: 05 JUN 25

Date In: 20 OCT 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 05 JUN 25

Job #WINT2 - External

WINTERIZE-TT/CLASS C

Due to the winterization process, most refrigerator filters and water filters will need to be replaced. Because of the variability of filters, customers will be responsible for ordering/supplying the replacement filter for your unit at time of dewinterization in the spring.

Because of the number of different filters being used by manufacturers, Tri-Am RV cannot guarantee that we will have the correct filter in stock at time of the appt. Therefore, we recommend that you either pre-order your filters, or bring them with you at your appointment time.

Initial/Date: _____

Labor

Code	Description	Hours	Rate	Total
SP120140	WINTERIZE FRESH WATER SYSTEM	1	175.00	175.00

Parts

Part #	Description	Qty	Price	Total
13-1639	ANTIFREEZE -50	3	7.19	21.57

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	8.75	8.75

Subtotal for Job #WINT2: 205.32

Job #2 - External

QUOTE ON WASH

Subtotal for Job #2: 0.00

Job #3 - External

AWNING NOT CLOSING ALL THE WAY



Subtotal for Job #3: 0.00

Job #4 - External

COMPLAINT: CUSTOMER STATES OUTSIDE SHOWER ATTACHMENT IS WRONG. STATES THREE PEOPLE TRIED TO ATTACH HOSE AND COULD NOT. CHECK AND ADVISE

CORRECTION: NO ISSUE FOUND. WE WILL SHOW CUSTOMER HOW TO ATTACH IT AT PICK UP

Subtotal for Job #4: 0.00

Job #ROOFINS - External

COMPLEMENTARY ROOF INSPECTION

CHECK CAULKING _____

CHECK SKYLIGHTS _____

CHECK ROOF VENTS _____

CHECK LUBE & ANTENNA _____

CHECK SATELLITE _____

CHECK RUBBER _____

Subtotal for Job #ROOFINS: 0.00

Job #6 - External

CHECK TIRE PRESSURE

Subtotal for Job #6: 0.00

Job #7 - External

TV WILL NOT WORK ON WIFI

Subtotal for Job #7: 0.00

Parts Total:	21.57
Labour Total:	175.00
Sublet Total:	0.00
Extras Total:	8.75
Tax Total:	20.02
Estimate Total:	225.34

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 26 Oct 2026

