



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 74027-1
Promised Date:
43 NOV 26

74027-1

WO #: 74027-1

Customer Name: 1000 - MYERS "RV"
CENTER, INC.

Completed Date:
Invoice#:
Author: ADVISOR
Stock Desc: 9757 2027 CRUSADER
2SUITE
Serial#: 128804
Chassis#: 5ZT3CS9B7VG128804
Miles/Hrs:
Tag#:
Purchased Date:
Warranty Date:

Date In: 27 OCT 26
Time In:

Job #01 - Warranty

COMPLAINT: Floor damaged seems that a staple is coming up from the floor

CAUSE: Floor damaged seems that a staple is coming up from the floor

CORRECTION: Need to order a roll of the same flooring material. Once new floor material is here we need to cutout the damaged tile very carefully along the false grout lines in a way that we can place the new tile in place easily with no ugly gaps or cracks . Once damaged piece of floor is removed we need to remove the staple that caused the issue and smooth out the area by sanding flat again .once raw floor is prepped and ready for new floor tile we need to start to four out the new piece fork the roll of flooring we will have to order . Need to lay out and find the exact same floor tile o the new floor that way it matches with the rest of the floor. Once new floor tile is cut out we need to apply floor glue to the area and lay down the floor patch .once patch is placed we need to roll smooth to insure the glue is making good contact and to roll away any excess glue and make flat .once floor parch is glued down we need to aloow time for the glue to dry befor we seal the edges of patch with seam sealer . Once the edges are sealed with seam seal need to clean off any leftover adhesives .requesting 2 hours for floor repair and repair of floor itself with the staple coming thru . See pics for more info

Labor

Job #	Description	Total
01	MISC LABOUR CODE (WARRANTY)	N/C
Subtotal for Job #01:		0.00

Job #02 - Warranty

COMPLAINT: Grey tank handle missing

CAUSE: unknown

CORRECTION: Need to order and replace the middle grey tank release handle .see pics requesting 5 mins for install

Labor

Job #	Description	Total
02	MISC LABOUR CODE (WARRANTY)	N/C
Subtotal for Job #02:		0.00

Job #03 - Warranty

COMPLAINT: Back bedroom door damaged from ladder

Customer #: 1000
MYERS "RV" CENTER,
INC.,

1000

74027-1

Customer #: 1000
 MYERS "RV" CENTER,
 INC.,

1000

CAUSE: The ladder in the back bedroom fell off the side of the bed, hitting and damaging the door during transport.

CORRECTION: Need to order new door and replace . Will need to remove all securing screw on old door and remove . Once old door is removed from unit we need to remove all door hardware ,hinges x3 and door handle once all hardware is removed we need to transfer old hardware onto the new door .need to install the door handle on new door . Need to install old hinges on new one etc. requesting 45 mins for replacement.see pictures .

Labor

Job #	Description	Total
03	MISC LABOUR CODE (WARRANTY)	N/C

Other Services

Code	Description	Qty	Price	Total
SSW	SHOP SUPPLIES - WARRANTY	1.00	N/C	N/C

Subtotal for Job #03: 0.00

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 0.00

NOTICE

Due to limited storage space, a storage fee of \$15 per calendar day will be charged if the unit is not picked up within 48 hours after the customer is notified that the work is complete.

Effective January 12, 2026, a 3% surcharge will be applied to all credit card transactions.

MANUFACTURER WARRANTIES AND SERVICE CONTRACTS MAY NOT COVER DIAGNOSTIC TIME WHEN NO COVERED PROBLEM OR DEFECT IS FOUND. THE CUSTOMER IS RESPONSIBLE FOR ANY DIAGNOSTIC CHARGES NOT PAID BY THE MANUFACTURER OR SERVICE CONTRACT PROVIDER.

FREEZE DAMAGE AND WINTERIZATION

The customer is responsible for ensuring that the unit is properly winterized before leaving it with Myers RV Center, Inc. Myers RV Center, Inc. is not responsible for freeze damage to the unit or to its plumbing, water, appliance, or related systems while the unit is awaiting service, undergoing service, awaiting parts, or awaiting pickup.

If the customer wants Myers RV Center, Inc. to winterize the unit, the customer must submit the request by text message to the Service Department and receive confirmation that the request has been received and accepted. A verbal request is not sufficient and will not be considered authorization to perform winterization. Winterization is a separate, billable service and will not be performed automatically. Myers RV Center, Inc. is not responsible for freeze damage occurring before the requested winterization service has been completed.

LOSS OR DAMAGE

Although Myers RV Center, Inc. takes reasonable precautions to protect the unit while it is in our possession, we are not responsible for loss of or damage to the unit or its contents caused by fire, theft, severe weather, or any other cause beyond our reasonable control. Customers should remove or secure valuables, including firearms, cameras, jewelry, cash, and personal belongings, before leaving the unit for service.

AUTHORIZATION

I authorize Myers RV Center, Inc. to perform the repair work described in this work order and to furnish the parts and materials reasonably necessary to complete the authorized work. I understand that Myers RV Center, Inc. is not responsible for delays caused by parts availability, supplier or manufacturer delays, shipping delays, or other circumstances beyond its reasonable control.

I authorize Myers RV Center, Inc., its employees, and its authorized vendors to operate the vehicle on streets and highways when reasonably necessary for testing, inspection, diagnosis, transportation, or delivery to a subcontracted service provider.

I acknowledge an express mechanics lien on the vehicle described in this work order to secure payment for authorized repairs, parts, materials, storage fees, and other amounts lawfully due.

Customer Signature : _____

Date: 27 Oct 2026

W/O: 74027-1
Promised Date: 13 NOV 26

74027-1

Customer #: 1000
MYERS "RV" CENTER,
INC.,

1000

Customer Work
Order