



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

WO #: 27901

Customer: 94750 - EADES, JERRY
Address: 2240 VAN HILL RD
GREENEVILLE, TN
37745
Home Phone: (540) 819-3596
Work Phone:
Author: S.DAVIS
Location: IH
Invoice #:

Stock #: 11268
Stock Desc: 2026 TT KZ-RV SPORTSMEN SE
292RBKSE
Model: 292RBKSE
Serial #: 4EZTU3025T5010694
Chassis #:
Mileage:
Key #:
Req'n #:
License #:
Trim:

Purchase Date: 30 OCT 26
Date In: 27 OCT 26
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date: 30 OCT 26

Job #1 - Warranty

COMPLAINT: FURNACE CONTINUES TO RELIGHT AND THEN EVENTUALLY SHUTS OFF.

CAUSE: FOUND THERMOSTAT PROVIDING 13.3V TO THE FURNACE SIGNALING TO ACTIVATE FURNACE. AS SOON AS GAS VALVE IS OPENED ON FURNACE VOLTAGE AT THERMOSTAT DROPS BELOW 9.0V CAUSING FURNACE TO DEACTIVATE. ONCE GAS VALVE CLOSES THE VOLTAGE COMING FROM THERMOSTAT RISES BACK TO 13.3V WHICH REACTIVATES FURNACE AGAIN AND REPEATS. THERMOSTAT IS CAUSE FOR VOLTAGE DROPPING. TESTED FURNACE TO CONFIRM THE ISSUE IS SOLEY THERMOSTAT BY OVERRIDING FURNACE USING BLUE WIRES CONNECTED TOGETHER.

CORRECTION: REPLACE THERMOSTAT AND TEST
Labor and Diag 1.2

Subtotal for Job #1: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 27 Oct 2026

