



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27913



WO #: 27913

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11379

Stock Desc: 2027 TT FOREST RIVER

ROCKWOOD ULTRA 2921RL

Model: 2921RL

Serial #: 4X4TRLL22VZ203311

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 30 OCT 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

Job #1 - Warranty

COMPLAINT: CABINET STILE OVER TV IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: FILL AND COLOR BLEND AREA

LABOR .10

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: CABINET NEXT TO STOVE IS SCRATCHED IN SEVERAL PLACES AND THE
SCRATCHES ARE DEEP IN SOME AREAS

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE CABINET DOOR

LABOR .50

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: ELECTRICAL OUTLET IS STICKING OUT FROM WALL

CAUSE: NOTED ON DAF

CORRECTION: RESECURE OUTLET INTO PLACE CORRECTLY.

LABOR .10

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: FRONT WINDOW GIMP HAS CAME LOOSE

CAUSE: NOTED ON DAF

CORRECTION: RESECURE BACK INTO PLACE

LABOR .20

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Subtotal for Job #4: 0.00

W/O: 27913

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00


WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X


MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 30 Oct 2026

Customer Signature : _____



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Customer Work Order

