FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	**CLAIM STATUS**	Authorized
BASDEN RV CENTER INC		**CLAIM**	1404605
DBA AMERICAN RV CENTER		**CLAIM ORIGIN**	WEB
600 E BASELINE ROAD		**ORIGINAL CLAIM ID**	
EVANSVILLE, IN 47725		**VIN**	4X4TCKY22NK084625
USA		**CHASSIS VIN**	
		MILEAGE	0
		SITE/WAREHOUSE	094 / 094A
Labor rate:	$150.00	**ITEM #**	CKT23DBH-94
OWNER INFORMATION		**DEALER RO #**	69739
		CLAIM START DATE	01/27/2023
		CLAIM END DATE	01/01/1900
Retail Date of Purchase		**WARRANTY EXPIRATION DATE**	

Claim Line Details

Labor

Line# 1

Operation Code
20-69-01-00-000703

Operational Description
Hold Back Latch, Catch, or Magnet - Exterior/Compartment Doors/ Replace/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2023-01-27 14:20:34 :: FRONT COMPARTMENT HOLD BACK BROKEN DRONT COMPARTMENT HOLD BACK BROKEN. Spring broken in hold back. Removed broken compartment door hold back. Installed new compartment door hold back.

Model #		**Dlr Sub Hrs**	0.10	**Sub Labor Amt**	$15.00
Serial #		**Appr Hrs**	0.10	**Appr Labor Amt**	$15.00

Notes

Labor

Line# 2

Operation Code
10-12-01-00-000262

Operational Description
Slide Out Box - Frame & Chassis/Slide Out System - Lippert/Replace/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2023-01-27 14:21:20 :: SLIDE ROOM FRONT OF THE ROOM HAS A SCREW POKING THRU SLIDE ROOM FRONT OF THE ROOM HAS A SCREW POKING THRU THE BOTTOM. Removed front dinette seat cushion and bottom. Removed slide out drawer for access to screw. Removed drawer slide mounting screw and replaced with a shorter screw. Checked bottom of slide out. Screw is not poking thru now. Put black silicone in hole to seal.

Model #		**Dlr Sub Hrs**	0.60	**Sub Labor Amt**	$90.00
Serial #		**Appr Hrs**	0.60	**Appr Labor Amt**	$90.00

Notes
repaired

Submitted	Labor Amt	$105.00	**Approved**	Labor Amt	$105.00
	Parts & Freight	$0.00		Parts & Freight	$0.00
	Total	$105.00		Total	$105.00

DEALER SIGNATURE **DATE**

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER SIGNATURE **DATE**

All repairs described have been inspected and are satisfactory.