



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69919
Promised Date:
20 FEB 23

CUSTOMER WORK ORDER

WO #: 69919

Customer: 1000 - BASDEN'S
AMERICAN RV -

Tag:

Author: BH

Location: 0324 SEE IF PARTS ARE
HERE YET

Stock #: 11094

Stock Desc: 2022 TT COACHMEN
CATALINA 293QBCKLE

Chassis #: 5ZT2CAUB0NX026077

Serial #: 5ZT2CAUB0NX026077

Mileage: 0

Licence:

Invoice #:

Date In: 23 FEB 23

Promised: 28 FEB 23

Date Sched:

Completed: 23 MAR 23

Warr. Date:

Job #1 - Warranty

COMPLAINT: OUTSIDE FRIDGE DOOR SEAL DOESNT SHUT ALL THE WAY

CAUSE: OUTSIDE FRIDGE DOOR WONT SHUT ALL THE WAY AS THE SEAL HAD COME LOSE,
REATTACHED SEAL AND IT SHUT RIGHT

CORRECTION: OUTSIDE FRIDGE DOOR WONT SHUT ALL THE WAY AS THE SEAL HAD COME
LOSE, REATTACHED SEAL AND IT SHUT RIGHT

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	32.00

Subtotal for Job #1: 32.00

Job #2 - Warranty

COMPLAINT: ENTRY DOOR AND SCREEN WONT OPEN AT THE SAME TIME

CAUSE: ENTRY DOOR AND SCREEN WONT OPEN AT THE SAME TIME, DUE TO LATCH ON SCREEN
DOOR BEING INSTALLED CRROKED. TEMOVED SCREEN DOOR LATCH AND REINSTALLED TO THE
PROPER POSTION

CORRECTION: ENTRY DOOR AND SCREEN WONT OPEN AT THE SAME TIME, DUE TO LATCH ON
SCREEN DOOR BEING INSTALLED CRROKED. TEMOVED SCREEN DOOR LATCH AND
REINSTALLED TO THE PROPER POSTION

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	16.00

Subtotal for Job #2: 16.00

Job #3 - Warranty

COMPLAINT: SLIDING BUNK DOOR

CAUSE: sliding bunk door was off the track removed track to readjust door and reattached track/stop and tested

CORRECTION: sliding bunk door was off the track removed track to readjust door and reattached track/stop and tested

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	48.00



Customer #:
1000



Subtotal for Job #3: 48.00

Job #4 - Warranty

COMPLAINT: BEDROOM DOOR RUBS

CAUSE: BEDROOM DORR WAS RUBBING DO TO HINGES OF DOOR NOT ALL THE WATY IN. SCREWED IN HINGES AND IT SOLVED THE PROBLEM

CORRECTION: BEDROOM DORR WAS RUBBING DO TO HINGES OF DOOR NOT ALL THE WATY IN. SCREWED IN HINGES AND IT SOLVED THE PROBLEM

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	32.00

Subtotal for Job #4: 32.00

Job #5 - Warranty

COMPLAINT: BUNKROOM ODS CABINET RUB

CAUSE: BUNKROOM CABNIET DOORS WERE RUBBING AS THEY WERE INSTALLED TO CLOSE TOGETHER. REMOVED ONE DOOR AND ADJUSTED POSTION. REMOVED LATCH AS WELL WHICH FIXED THE PROBLEM

CORRECTION: BUNKROOM CABNIET DOORS WERE RUBBING AS THEY WERE INSTALLED TO CLOSE TOGETHER. REMOVED ONE DOOR AND ADJUSTED POSTION. REMOVED LATCH AS WELL WHICH FIXED THE PROBLEM

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	32.00

Subtotal for Job #5: 32.00

Job #6 - Warranty

COMPLAINT: ENTRY DOOR SEAL COMING OFF

CAUSE: ENTRY DOOR SEAL WAS COMING OFF NEEDED SOM ADHESIVE. ADDED SOME ADHESIVE AND STUCK BACK ON

CORRECTION: ENTRY DOOR SEAL WAS COMING OFF NEEDED SOM ADHESIVE. ADDED SOME ADHESIVE AND STUCK BACK ON

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	32.00

Subtotal for Job #6: 32.00

Job #7 - Warranty

COMPLAINT: UNDER SINK 2 AREAS IN THE CABINET THERE IS WOOD LOOSE

CAUSE: under sink wood panel is lose do to it being chipped and broke needs new one

CORRECTION: under sink wood panel is lose do to it being chipped and broke needs new one

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	64.00

Parts

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------



7815 PANELING, HDF 2.7 MM X 4' X 8' CHILI 32.00 1.40 44.80
TEAK F4E 451237 MC 2022

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT	1.00	344.11	344.11

Subtotal for Job #7: 452.91

Parts Total: 44.80
Labour Total: 256.00
Sublet Total: 0.00
Extras Total: 344.11
WORK ORDER TOTAL: 644.91

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 23 Mar 2023

W/O: 69919
Promised Date:
28 FEB 23



Customer #:
1000

