

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1454862
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CARB3PU041735
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$160.00	SITE/WAREHOUSE	103 / 103
OWNER INFORMATION		ITEM #	CAT261BH-8
		DEALER RO #	69958
		CLAIM START DATE	03/10/2023
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor
Line# 1

Operation Code
20-69-01-00-000706

Operational Description
Compartment Door - Exterior/Compartment Doors/Replace/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2023-03-10 16:31:44 :: OUTSIDE RIGHT HAND BACK COMPARTMENT DOOR HITTING FRAME AND HARD TO CLOSE hole in wall is not square, remove door, remove corner block mark metal and hand trim metal back to size, cut wood frame back, pant freash cut wood, install corner block, install door and cap seal around door,

Model #
Serial #

Dlr Sub Hrs
Appr Hrs

0.50
0.50

Sub Labor Amt
Appr Labor Amt

\$80.00
\$80.00

Notes
AUTHORIZED AS REQUESTED

Labor
Line# 2

Operation Code
01-70-147-001769

Operational Description
TV Coax Cable - Replace/Appliances/Television

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2023-03-10 16:33:07 :: NO TV SIGNAL ON INSIDE OR OUTSIDE MISS WIRED AND SHORTED WIRES AT BOOSTER TEST ANTENA FOR TV, NO SIGNAL FOUND START TESTING AND TRACING WIRES FOUND ANTENA WIRE IS CONETED TO TV #2 OUT ON BOOSTER, CABLE IN WIRE ON ANTENA IN ON BOOSTER, WIRE RUNNING TO RADIO IS SHORTED, PUT NEW ENDS ON WIRE

Model #
Serial #

Dlr Sub Hrs
Appr Hrs

1.50
1.50

Sub Labor Amt
Appr Labor Amt

\$240.00
\$240.00

Notes
AUTHORIZED AS REQUESTED

Labor
Line# 3

Operation Code
02-30-101-001076

Operational Description
Hinged Passage Door - Adjust/Interior/Interior Doors

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2023-03-13 11:02:39 :: BATHROOM DOOR WILL NOT CLOSE ALL THE WAY AT THE BOTTOM bathroom door hard to latch and walls not lined up with bottom of door sticking out of door frame by 3/4 in, and top is in all the way remove door and found 4 set of screw holes for hinges, remove door jam and found red marking tape on door frame, remove wall board and remove mounting scres for wall section, move bottom of wall section about 3/8 of an in all i can move with out rebuilding unit wall has bath sink cabinet on 1 side and refer cabinet on other side, pull staples out of trim and wall board to reuse we do not have any thing to match, install all parts and hang door, door latch's, to get door in jam all the way the other side of the wall will need the same thing,

Model #
Serial #

Dlr Sub Hrs
Appr Hrs

2.50
2.50

Sub Labor Amt
Appr Labor Amt

\$400.00
\$400.00

Notes

Submitted	Labor Amt	\$720.00	Approved	Labor Amt	\$720.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$720.00		Total	\$720.00

DEALER

SIGNATURE

DATE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

SIGNATURE

DATE

All repairs described have been inspected and are satisfactory.