



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 72481
Promised Date:
20 DEC 23



Customer #: 1000
BASDEN'S AMERICAN RV,

CUSTOMER WORK ORDER

WO #: 72481

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag: BH - PARTS ORDERED PER BEN.
12-18

Author: BH

Location: 0119 BH TO CLOSE

Stock #: 10744

Stock Desc: 2023 TT COACHMEN
CATALINA SUMMIT SERIES 164RB

Chassis #: 5ZT2CAEC5PK005555

Serial #: 5ZT2CAEC5PK005555

Mileage: 0

Licence:

Invoice #:

Date In: 04 DEC 23

Promised: 30 DEC 23

Date Sched:

Completed: 24 JAN 24

Warr. Date:

Job #1 - Warranty

COMPLAINT: WATER HEATER LATCH BROKEN

CAUSE: Latch was missing from flange. Replaced latch.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	32.00

Parts

Part #	Description	Qty	Price	Total
20-0235	00225 WATER HEATER DOOR LATCH	1.00	3.90	3.90
H201	H201 ROLLER CATCH WITH PRONG	1.00	3.19	3.19

Subtotal for Job #1: 39.09

Job #2 - Warranty

COMPLAINT: OFF DOOR SIDE COMPARTMENT PANEL COMING OFF

CAUSE: Removed panel. Secured panel together with screws. Installed panels inside compartment

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	48.00

Subtotal for Job #2: 48.00

Job #3 - Warranty

COMPLAINT: BATTON TRIM ON BOTH SIDES OF THE ENTRY DOOR ARE LOOSE

CAUSE: S3cured trim with Brad nails and filled holes with putty

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	32.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00





Subtotal for Job #3: 32.00

Job #4 - Warranty

COMPLAINT: DAMAGE TO THE LEFT OF THE FRIDGE BOTTOM WOOD

CAUSE: Stile has been gouged. Needs replaced. 2 inch wide. 7 ft tall.

CORRECTION: .

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	41.60
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	38.40
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	16.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Parts				
Part #	Description	Qty	Price	Total
F100285185	STILE, LC 18MM" X 2" X 8' SQUARE CHI	8.00	0.62	4.96
F100282071	GE STAINLESS FREEZER DOOR 2022 FOR	1.00	397.83	397.83

Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-STILE	1.00	32.41	32.41

Subtotal for Job #4: 531.20

Job #5 - Warranty

FREEZER DOOR HAS DENT

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	32.00

Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-FREEZER DOOR	1.00	37.77	37.77

Subtotal for Job #5: 69.77

Job #6 - Warranty

COMPLAINT: OUTDOOR SPEAKER NOT WORKING

CAUSE: Pulled radio and checked connections. The amp is not working on the "B" side. Checked speaker and wires leading to radio. Another job was made since it isn't a "speaker" issue.

CORRECTION: .

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Subtotal for Job #6: 0.00



W/O: 72481
Promised Date: 30 DEC 23

Parts Total:	409.88
Labour Total:	240.00
Sublet Total:	0.00
Extras Total:	70.18
WORK ORDER TOTAL:	720.06

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 24 Jan 2024

Customer Signature : _____



Customer #: 1000
BASDEN'S AMERICAN RV,

