FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	**CLAIM STATUS**	Authorized
BASDEN RV CENTER INC		**CLAIM**	1797954
DBA AMERICAN RV CENTER		**CLAIM ORIGIN**	WEB
600 E BASELINE ROAD		**ORIGINAL CLAIM ID**	
EVANSVILLE, IN 47725		**VIN**	5ZT2CAZB8NX026806
USA		**CHASSIS VIN**	
		MILEAGE	0
Labor rate:	$160.00	**SITE/WAREHOUSE**	205 / 205
OWNER INFORMATION		**ITEM #**	ACAT343BHTSLE
DAVID FISCHER		**DEALER RO #**	72616
		CLAIM START DATE	01/24/2024
5512 RYAN LANE		**CLAIM END DATE**	01/01/1900
Evansville, IN 47712			
USA			
Retail Date of Purchase	10/17/2022	**WARRANTY EXPIRATION DATE**	10/17/2023

Claim Line Details

Labor

Line# 1

Operation Code
30-100-01-00-001050

Operational Description
Cabinet Stiles - Interior/Cabinetry/Replace/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2024-01-24 11:00:54 :: THIS WAS ADDED STUFF THIS THIS CLAIM CUSTOMER CAME BACK AND WANTED FIXED BECAUSE IT WAS NOT FIXED FROM THE CLAIMS CLAIM 1714064 CLAIM 1651630 ---------- BATHROOM CABINET WOOD IS DAMAGED AND NEEDS FIXED Remove toilet. Remove cabinet door and access panel. Remove damaged cabinet front. Remove cabinet front to the left of the sink. Build two new frames and install. Put door back and panel. Silicone around bottom. Put toilet back.
---------- TO THE RIGHT OF THE STOVE THE WOOD IS DAMAGED Remove water heater access panel. Remove stove and cut 12 v wires. Remove shelf below stove. Remove damaged 3 1/4 stile. Cut and install new stile. Staple back braces. Wire up stove and put back. Put panel back. Do drop test on lp. Remove cabinet doors above converter. Remove customers goods and put them in boxes. Remove four shelves. Remove converter. Remove outlet. Unscrew cabinet front from wall. Pry cabinet front from shelves. Cut off staples on 3/4" supports. Remove damaged stile. Cut new stile. Staple back on supports. Install front back and staple. Remove cabinet door. Remove stereo. Remove outlet. Remove both shelves. Remove damage stile. Cut new stile. Install. Put door and shelves back. Put radio back.

Model#		**Dlr Sub Hrs**	15.00	**Sub Labor Amt**	$2,400.00
Serial#		**Appr Hrs**	10.00	**Appr Labor Amt**	$1,600.00

Notes
EXCESSIVE AMOUNT REQUESTED
CHANGED TO SIMILAR REPAIR TIME

Submitted	Labor Amt	$2,400.00	**Approved**	Labor Amt	$1,600.00
	Parts & Freight	$0.00		Parts & Freight	$0.00
	Total	$2,400.00		Total	$1,600.00

DEALER SIGNATURE **DATE**

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER SIGNATURE **DATE**

All repairs described have been inspected and are satisfactory.