



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73830



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 73830

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0615 CHECK PREAUTH

Stock #: 11408
Stock Desc: 2024 TT COACHMEN
CATALINA SUMMIT SERIES 261BHS
Chassis #: 5ZT2CARB9RU043928
Serial #: 5ZT2CARB9RU043928
Mileage: 0
Licence:

Invoice #:
Date In: 03 JUN 24
Promised:
Date Sched:
Completed: 14 JUN 24
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER - 4 HR PDI

CAUSE: PDI new trailer

CORRECTION: Checked
Water and plumbing systems
Electrical system
12vdc system
LP system, passed leak test
Interior and exterior
Lights
Running gear
Breakaway switch
65 PSI in tires

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JH	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: AWNING NOT OPENING. NEEDS SOLARA SPRING
KIT

CAUSE: Awning not opening correctly

CORRECTION: Install a tolerance spring kit to help arms open.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	85.00



Parts

Part #	Description	Qty	Price	Total
2022123083	SOLERA HELPER SPRING KIT	1.00	15.51	15.51

Subtotal for Job #1: 100.51

Job #2 - Warranty

COMPLAINT: SPRAY PORT WON'T CLOSE

CAUSE: Spray port won't close

CORRECTION: Remove screws and install tapered screws so the lid doesn't hit screw head

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	51.00

Subtotal for Job #2: 51.00

Job #3 - Warranty

COMPLAINT: SCREW PULLED THRU METAL ON OFF DOORSIDE
FRONT LOWER WRAP

CAUSE: Screw pulled thru j wrap on left front

CORRECTION: Remove screw and add a painted flat washer and reinstall screw

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	17.00

Subtotal for Job #3: 17.00

Job #4 - Warranty

COMPLAINT: BLACK GOOP ON TOP OF RUBBER ON SLIDEROOM

CAUSE: Black goop on the side of rubber roof of slideroom

CORRECTION: Use putty buddy and roof cleaner to remove black sealer from rubber roof edge.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JH	17.00

Subtotal for Job #4: 17.00

Parts Total: 15.51
Labour Total: 170.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 185.51

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.



Customer #: 1000
BASDENS AMERICAN RV,



Customer Signature : _____

Date: 14 Jun 2024

W/O: 73830



Customer #: 1000
BASDENS AMERICAN RV,



Customer Work
Order

