# FOREST RIVER WARRANTY CLAIM FORM

| | | | |
|---|---|---|---|
| **DEALER ACCOUNT #** | 0005106 | **CLAIM STATUS** | Authorized |
| BASDEN RV CENTER INC | | **CLAIM** | 1980827 |
| DBA AMERICAN RV CENTER | | **CLAIM ORIGIN** | WEB |
| 600 E BASELINE ROAD | | **ORIGINAL CLAIM ID** | |
| EVANSVILLE, IN 47725 | | **VIN** | 5ZT2CAGC5SK008624 |
| USA | | **CHASSIS VIN** | |
| | | **MILEAGE** | 0 |
| **Labor rate:** | $170.00 | **SITE/WAREHOUSE** | 203 / 203 |
| **OWNER INFORMATION** | | **ITEM #** | BCAT184BHS |
| | | **DEALER RO #** | 74132 |
| | | **CLAIM START DATE** | 07/10/2024 |
| | | **CLAIM END DATE** | 01/01/1900 |
| **Retail Date of Purchase** | | **WARRANTY EXPIRATION DATE** | |

## Claim Line Details

### Labor

**Line# 1**

**Operation Code**
40-196-24-11-001297

**Operational Description**
Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical

**Complaint, Cause, Correction**
Original Note : bhoffman@americanrvcenter.com, 2024-07-10 15:52:06 :: WIRING PULLING OUT FROM UNDER SLIDEROOM Wiring pulling out from under slideroom Reattach wiring to slideroom so it does come out from under slideroom

**Model#**

**Serial#**

| | | | |
|---|---|---|---|
| **Dlr Sub Hrs** | 0.50 | **Sub Labor Amt** | $85.00 |
| **Appr Hrs** | 0.30 | **Appr Labor Amt** | $51.00 |

**Notes**
EXCESSIVE AMOUNT REQUESTED
CHANGED TO SIMILAR REPAIR TIME TO SECURE WIRES

| | | | | | |
|---|---|---|---|---|---|
| **Submitted** | Labor Amt | $85.00 | **Approved** | Labor Amt | $51.00 |
| | Parts & Freight | $0.00 | | Parts & Freight | $0.00 |
| | Total | $85.00 | | Total | $51.00 |

**DEALER SIGNATURE** **DATE**

I certify that I have performed these repairs consistent with Forest River Policies.

**CUSTOMER SIGNATURE** **DATE**

All repairs described have been inspected and are satisfactory.