



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74634



CUSTOMER WORK ORDER

WO #: 74634 (Appointment Date: 27 AUG 2024 - Time: 10:00am)

Customer: 54943 - LITTLEPAGE,
DONALD - 812-204-5261

Tag:

Author: BH

Location: 0910 CHECK PREAUTH

Stock #: 11382

Stock Desc: (11382) 2024 COACHMEN

CATALINA 243RBSLE

Chassis #: 5ZT2CANB2RU043498

Serial #: 5ZT2CANB2RU043498

Mileage:

Licence:

Invoice #:

Date In: 27 AUG 24

Promised:

Date Sched:

Completed: 31 AUG 24

Warr. Date: 29 JUN 24

Job #1 - Warranty

COMPLAINT: WATER IS LEAKING ABOVE THE ENTRY DOOR ON THE OUTSIDE MARKED WITH BLUE TAPE

CAUSE: Gutter seam is leaking. Applied silicone.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	34.00
Subtotal for Job #1:			34.00

Job #2 - Warranty

COMPLAINT: THE SEAL AT THE BOTTOM OF THE SHOWER IS NOT HOLDING WATER AND IT LETS IT RUN INTO THE FLOOR.

CAUSE: Shower surround isn't sealed. Applied silicone as needed and removed excess.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	34.00
Subtotal for Job #2:			34.00

Job #3 - Warranty

COMPLAINT: THERE IS TRIM ON THE CEILING IN THE BED ROOM HAS COME LOOSE AND YOU CAN SEE GAPS

CAUSE: There are staples on thr track that the trim sits in. Removed staples and secured trim.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	34.00
Subtotal for Job #3:			34.00

Job #4 - Internal

COMPLAINT: check water heater on gas and ele to make sure it works

Customer #: 54943
LITTLEPAGE, DONALD



CAUSE: Filled water heater. Tested electric heating element. The heating element is working. Tested 12 volt side. The ignitor sounds very weak. Removed the ignitor and pulled rods closer together and installed onto the water heater. Water heater fires up immediately.

CORRECTION: .

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Subtotal for Job #4:			0.00

Job #5 - Warranty

COMPLAINT: THE BACK SPLASH IS LOOSE AND IS FALLING OFF

CAUSE: Applied contact adhesive to the wall. Sealed edge with silicone

CORRECTION: .

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	17.00
Subtotal for Job #5:			17.00

Parts Total: 0.00
Labour Total: 119.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 119.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 04 Sep 2024

W/O: 74634



Customer #: 54943
LITTLEPAGE, DONALD

