600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74797
Promised Date: 30 SEP 24

CUSTOMER WORK ORDER

WO #: 74797
Customer: 43337 - WILL, CHRISTINA - 812-449-6158
Tag:
Author: PH
Location: 1009 BH TO CLOSE

Stock #: 11462
Stock Desc: 2025 TT FOREST RIVER CHEROKEE GREY WOLF 26DBH
Chassis #: 4X4TCKB21SK091814
Serial #: 4X4TCKB21SK091814
Mileage: 0
Licence:

Invoice #:
Date In: 16 SEP 24
Promised: 30 SEP 24
Date Sched:
Completed: 30 SEP 24
Warr. Date: 11 SEP 24

Customer #: 43337
WILL, CHRISTINA

Job #1 - Warranty

COMPLAINT: FRIDGE NOT COOLING, FREEZER DID. SHOWED EF CODE

CORRECTION: I PULLED THE FRIDGE OUT OF THE WALL. I TESTED THE VOLTAGE AND AMPS AT THE BACK OF THE FRIDGE. I REMOVED THE FAN FROM INSIDE THE FREEZER AND TESTED THE FAN MOTOR. I FOUND THAT THE FAN IS NOT WORKING. I ALSO FOUND THAT THE FRIDGE WAS ONLY DRAWING 5 AMPS MAX AND IT SHOULD BE AROUND 12 AMPS. I FILLED OUT THE FURRION FRIDGE CHECKLIST AND GAVE IT TO BEN. THEN PUT THE FRIDGE BACK IN THE WALL. I REPLACED THE FAN IN THE FREEZER AND LET THE FRIDGE RUN. THE FRIDGE RAN OVER NIGHT AND WHEN I CHECKED IT IN THE MORNING, THE FRIDGE WAS 48 AND THE FREEZER WAS 5. I HAD THE FRIDGE SET ON 5 OUT OF 10 AND I HAD THE FREEZER SET ON 5 OUT OF 10. IT IS NOW WORKING AS IT SHOULD.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	170.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	0.00

Parts

Part #	Description	Qty	Price	Total
9863	FAN ASSEMBLY KIT - LIPPERT	1.00	79.35	79.35

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-FAN ASSEMBLY	1.00	10.54	10.54

Subtotal for Job #1: 259.89

Job #2 - Internal

COMPLAINT: CURTAIN IN BACK FELL OFF, NEEDS PUT BACK UP. THEY TRIED AND IT FELL AGAIN

CORRECTION: I USED WALL ANCHORS IN THE CEILING IN THE PLACES THE SCREWS PULLED OUT. I REPLACED THE OTHER SCREWS WITH ONES 1/4" LONGER.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Subtotal for Job #2: 0.00

Job #3 - Internal

COMPLAINT: RUN A/C CUSTOMER STATED IT WILL NOT CYCLE A 2ND TIME

© 2024 Integrated Dealer Systems

CORRECTION: I FOUND THAT THE A/C UNIT IS WORKING AS IT SHOULD. THE ROOM TEMP SENSOR IS LOCATED IN THE A/C UNIT. NOT ON THE WALL. SO THE ROOM HAS TO GET 2-4 DEG. WARMER THAN THE A/C UNTI IS TO GET THE UNIT TO TURN BACK ON. IF THE FAN IS SET TO HIGH AND NOT AUTO, THE ROOM WILL MAINTAIN THE ROOM TEMP BETTER BY RECIRCULATING THE AIR IN THE ROOM. THIS WILL PULL THE ROOM AIR OVER THE TEMP SENSOR AND IT WILL TURN ON / OFF FASTER TO MAINTAIN THE ROOM TEMP BETTER.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Subtotal for Job #3: **0.00**

Parts Total:	79.35
Labour Total:	170.00
Sublet Total:	0.00
Extras Total:	10.54
WORK ORDER TOTAL:	**259.89**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 09 Oct 2024

Customer Work Order

W/O: 74797
Promised Date: 30 SEP 24

Customer #: 43337
WILL, CHRISTINA

© 2024 Integrated Dealer Systems