're-Authorization

10/22/20
11:42:42 a

e-Authorization number PA03752915 Reference no: 74937 Status: Approved Approved by anglr Approved date 10/11/2024

rvicing aler	Name	Address	VIN	Retail sold on
94	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDFHMP22SA740337	

Ju be of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	1216014A	Step - Fold Up	0.00	0.15	0.15		1	0.10	Complaint:ENTRY STEPS HITTING DOOR FRAME Cause:ENTRY STEPS HITTING DOOR FRAME Correction:Loosened stop mounting bolts and adjusted left side stop bracket. Added space between door frame and stop bracket to allow steps to fold out without hitting door frame. Adjusted several times to get bracket to clear and not hit door frame.
2	3100812A	Cabinet Door - Re	0.00	0.10			1	0.20	Complaint:STAPLE HOLES IN CABINETS IN BEDROOM NEED FILLED, FRONT NOSE AREA Cause:2 STAPLE HOLES IN CABINETS IN BEDROOM NEED FILLED, FRONT NOSE AREA Correction:Filled all staple holes in both front bedroom compartment. KRV - staple holes in cabinets are not puttied
e-Authorization number PA03752915					0.15				

r paper claims only use one pre-authorization number per warranty claim for
aple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the
amount authorized on the pre-authorization form and return to Keystone RV Company.