·e-Authorization

12/2/20
09:28:02 a

e-Authorization number PA03776504 Reference no: 75162 Status: Approved Approved by: stept Approved date 11/27/2024

rvicing aler	Name	Address	VIN	Retail sold on
94	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDFCGN2XS2502426	

Ju pe of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
2	2203214B	Power Roof Vents	0.00	0.20	0.20		1	0.20	Complaint:BATHROOM VENT FAN NOT WORKING Cause:BATHROOM VENT FAN NOT WORKING Correction:Removed ceiling trim and screen. Fan blade was pushed up against mounting bracket. pulled blade away from mounting bracket. Fan now runs. Remounted screen and switchg assembly. Remounted ceiling trim ring.
e-Authorization number PA03776504					0.20				

r paper claims only use one pre-authorization number per warranty claim for
aple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the