



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76373
Promised Date:
20 APR 25



CUSTOMER WORK ORDER

WO #: 76373 (Appointment Date: 01 APR 2025 - Time: 10:30am)

Customer: 54471 - BEASLEY, ERIC -
812-582-1673

Tag:

Author: BJW

Location: 0505 BH TO CLOSE

Stock #: 11296

Stock Desc: 2024 TT ALLIANCE RV
DELTA 281BH

Chassis #: 7M5TD3129RC302297

Serial #: 7M5TD3129RC302297

Mileage: 0

Licence:

Invoice #: 416898

Date In: 01 APR 25

Promised: 30 APR 25

Date Sched:

Completed: 30 APR 25

Warr. Date: 02 MAR 24

Job #1 - Warranty

COMPLAINT: CUSTOMER HAS TANKLESS W/H. EVERYTIME HE
TURNS IT ON, IT BLOWS A FUSE

CAUSE: Water has a
short in the control board

CORRECTION: Started at
the outside of the water heater to see
if it was on then tried to put a 15 amp
fuse in place and it popped. Went back
out to the outside of the water heater
and shut it off. Tried to put another 15
amp fuse in and it popped again.
Disconnected the positive wire on the
water heater. Put the volt meter on the
positive wire then to a ground and there
was continuity. At the control board on
the water heater it smells burnt. Would
recommend a new water heater, not sure
what else was damaged in the water
heater and touch pad.

Customer #: 54471
BEASLEY, ERIC



Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	129.50

Parts

Part #	Description	Qty	Price	Total
2022006595	Furrion Replacement RV Tankless Wate	1.00	105.99	105.99

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-CONTROLLER	1.00	11.58	11.58

Subtotal for Job #1: 247.07

Job #2 - Warranty

COMPLAINT: CUSTOMER ADVISES HE CAN NOT GET THE
SPRAY HOSE IN THE SPRAY PORT AT THE BACK



OF THE RV.

CAUSE: Spray port connection won't hold the hose in the quick connection.

CORRECTION: Took the spray port hose and put in the quick connection but didn't stay in place. Put in po for a new spray port connection.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	37.00

Parts				
Part #	Description	Qty	Price	Total
24404	Spray Port - O/S w/Metal MPT Connect	1.00	11.99	11.99

Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-SPRAY PORT	1.00	12.27	12.27

Subtotal for Job #2: 61.26

Job #3 - Internal

COMPLAINT: GOING TO THE BEDROOM FROM THE KITCHEN THE BLIND DOES NOT CATCH

CAUSE: Normal operation

CORRECTION: Checked every blind with service writer even the blind going to the bedroom from the kitchen.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: THE JWRAP IS SCREWED UNDER AROUND EXECT FOR THE GRILL AREA AND FRIDGE IT IS COMING LOOSE

CAUSE: J wrap below the outdoor kitchen is not secured properly.

CORRECTION: Took pictures of the j wrap not sitting in place. Unscrewed the black trim above the white j wrap that is on both sides of the outside kitchen door. Pushed the j wrap up about 1/8 inch then put staples in to hold the j wrap up. Screwed the trim back on and trimmed with silicone.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	37.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00

Subtotal for Job #4: 37.00

Job #5 - Internal

COMPLAINT: THE LIGHTS ON THE FRONT ARE HOLDING ALOT OF WATER. THIS IS THE LOWER LED STRIP LIGHTS.

CAUSE: No water found in the light strip

CORRECTION: Inspected the led light strip on the lower front cap. Found no water in the light or around. Did see voids, put silicone in the voids to prevent water settling.

W/O: 76373
Promised Date: 30 APR 25



Customer #: 54471
BEASLEY, ERIC



W/O: 76373
Promised Date: 30 APR 25



Customer #: 54471
BEASLEY, ERIC



Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Subtotal for Job #5:			0.00

Job #6 - External

COMPLAINT: RUN THE FURANCE WHILE WORKING ON IT TO MAKE SURE IT WORKS FINE

CAUSE: Furnace testing

CORRECTION: After the water repair tested the furnace. Went to the thermostat and powered on the furnace. Let the furnace run for 5 mins. Shut off the furnace and went to the lp tanks to shut off. Found no problem with the furnace, works as should.

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)		SAR	N/C
Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
Subtotal for Job #6:				0.00

Job #SUMMER - External

COMPLAINT: DE-WINTERIZE UNIT

CAUSE: Dewinterizing and testing the water heater after repair

CORRECTION: Connected the hose to the city water connection. Put water in fresh tank. Flushed out the kitchen faucet, bathroom faucet, toilet, shower, spray port x3. Tested the water heater as well. Drained the black and grey tanks.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Other Services			
Code	Description	Qty	Price
SS	SHOP SUPPLIES	1.00	N/C
Subtotal for Job #SUMMER:			0.00

Parts Total:	117.98
Labour Total:	203.50
Sublet Total:	0.00
Extras Total:	23.85
WORK ORDER TOTAL:	345.33

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 05 May 2025

