

BASDEN RV CENTER, INC dba AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 77388  
MANUFACTURER'S CLAIM #:

Manufacturer: 52215 - ALLIANCE RV, LLC  
Customer: 50981 - LARRY COOMES  
Address: 15245 KINGSMONT DR EVANSVILLE, IN

47725

Phone: 812-484-9361

Stock Number: 11571 - 2025 DELTA 294RK 7M5TD3322SC305724

VIN: 7M5TD3322SC305724 HIN: SER#: 7M5TD3322SC305724

Mileage: 0

Work Order Comp: 31 JUL 25

Auth. No:

Dealer #:

Warr. Date: 29 JUL 25

Work Order Date: 25 JUL 25

Inv #: 420781

\*\*\*\*\*  
WO #      Job #      Description      JOB INFORMATION  
\*\*\*\*\*  
77388      1      THE SHOWER DRAIN IS LEAKING  
                 Shower drain pipe was not attached and leaking  
                 On doing my flushing the water lines found a leak coming from  
                 under the shower. And I found that the pipe was not attached. So  
                 I had to remove the shower surround and the shower tub to cut the  
                 pipe off. Add new pipe and connect it properly.let the glue set  
                 up over night. And the silicone around the shower curtain. Tested  
                 it this morning and no leaks. Works properly now  
  
77388      2      WHEN RUNNING WATER PUMP THE LIGHTS FLICKER  
                 Lights flicker when running the water pump  
                 I went straight to the ground wire on the water pump. Disconnect  
                 the ground wire and ran it straight to a ground by it self the  
                 lights did not flicker. So I checked the connector where it was  
                 at and put the wire back in the same connector and ran the water  
                 pump and lights did not flicker. So it was a bad connection. So  
                 they system works properly now.  
  
77388      3      REAR AWNING ARM HEAD IS HITTING ARM AND NOT LETTING IT CLOSE  
                 Rear awning arm not closing properly  
                 Loosened the awning arm and shifted the arm just a bit so the  
                 awning would close properly. It now works properly

\*\*\*\*\*  
Part No      Job#      Description      PARTS      Qty      Price      Total  
\*\*\*\*\*  
43108      1      1.5" PIPE COUPLER           2.00      2.99      5.98

Claim : 77388

\*\*\*\*\*  
 Part No            Job#    Description            PARTS                            Qty       Price       Total  
 \*\*\*\*\*

\*\*\*\*\*  
 Lab Code    Job#    Description            LABOUR                            Hrs       Rate       Total  
 \*\*\*\*\*  
 Z990            1    MISC LABOUR CODE (EXTERNAL)                            0.00      185.00       0.00  
 Z990            1    MISC LABOUR CODE (EXTERNAL)                            0.50      185.00       92.50  
 Z990            1    MISC LABOUR CODE (EXTERNAL)                            2.00      185.00      370.00  
 Z990            2    MISC LABOUR CODE (EXTERNAL)                            0.18      185.00       33.30  
 Z990            2    MISC LABOUR CODE (EXTERNAL)                            0.02      185.00       3.70  
 Z990            3    MISC LABOUR CODE (EXTERNAL)                            0.30      185.00      55.50

Parts Total:            5.98  
 Labour Total:          555.00  
 Sublet Total:          0.00  
 Extras Total:          0.00

>>>> Claim Total:       560.98

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_