BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 77416
MANUFACTURER'S CLAIM #:

Manufacturer: 52215 - ALLIANCE RV, LLC
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11646 - 2026 DELTA 292RL 7M5TD3320TC307179
VIN: 7M5TD3320TC307179 HIN: SER#: 7M5TD3320TC307179
Mileage: 0 Work Order Comp: 27 SEP 25
Auth. No: Dealer #:
Warr. Date: Work Order Date: 29 JUL 25 Inv #: 422549

WO #	Job #	Description	JOB INFORMATION
77416	2	THE COLD WATER LOW POINT DRAIN VALVE IS BROKEN	Broken low point valve Saw low point valve had broken. Removed old valve and replaced with new
77416	6	SCATCH ON BOTTOM LEFT CORNER OF ENTRY DOOR	Scratch on entry door glass During pdi of the unit I noticed scratches on, the glass of entry door. Pictures taken and parts request put in. New door arrived removed screws in old door after taking screw cover off. Removed screws inside door. Once screws were out slowly worked door loose from putty. Once putty was loose removed door. Excess putty was still on unit removed what was possible with putty knife and use mineral spirits to get rest of putty up. Putty mad a lot of mess on unit and had to clean up blac, marks all around door of unit. Removed silicone around top of door. Once all putty and silicone was removed unboxed door. Added putty to new door and stuck to unit. Ran a couple screws in unit to make sure it was square. Once it was checked ran rest of screws in door. Once all screws were in ran screw cover over both sides of door. Once screw cover was on added top ring and shoot screws in to secure to door. Added decal with soapy water to attach to door. Ran bubbles out and soaked outside of decal as well let sit over night to stich to door. Cut excess screw cover off. Adjusted steps latch to new door. Siliconed top ring of door. Door open and shuts well

Claim : 77416

WO #	Job #	Description JOB INFORMATION
77416	4	THE PUMP IS NOT WORKING RIGHT Pump not working During pdi of the unit noticed the water pump wouldn't work. Would only pulse and never run correctly. Pictures taken parts request put in

Part No	Job#	Description PARTS	Qty	Price	Total
ESC30879	2	30879 Shut Off Valve; PEXLock; St	1.00	8.99	8.99
32530	6	Door - Entry - 28 x 72 - RH - Gla	1.00	406.99	406.99
33614	6	DECAL - DOOR LGND - DELTA 2026	1.00	8.28	8.28
HNG5850	6	PUTTY TAPE - ROLL	1.00	7.49	7.49
LIP326192	6	76IN SNAP TRIM SCREW COVER, BLACK	2.00	9.87	19.74
34901	4	PUMP - WATER - 12V	0.00	41.12	0.00
333426	4	Pump - Water - Revolution - 12V -	1.00	57.28	57.28

Lab Code	Job#	Description LABOUR	Hrs	Rate	Total
Z990	2	MISC LABOUR CODE (EXTERNAL)	0.20	185.00	37.00
Z990	6	MISC LABOUR CODE (EXTERNAL)	0.00	185.00	0.00
Z990	6	MISC LABOUR CODE (EXTERNAL)	0.00	185.00	0.00
Z990	6	MISC LABOUR CODE (EXTERNAL)	0.00	185.00	0.00
Z990	6	MISC LABOUR CODE (EXTERNAL)	0.00	185.00	0.00
Z990	6	MISC LABOUR CODE (EXTERNAL)	1.00	185.00	185.00
Z990	6	MISC LABOUR CODE (EXTERNAL)	0.00	185.00	0.00
Z990	4	MISC LABOUR CODE (EXTERNAL)	0.50	185.00	92.50

Parts Total:	508.77
Labour Total:	314.50
Sublet Total:	0.00
Extras Total:	0.00
>>>>> Claim Total:	823.27

Customer Signature:_____ Date: _____